

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000018/T1GA3Q2

Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800059659
Claimant Vehicle No :	SLT8222B	Insured Vehicle No :	SLZ9512B
Date of Loss:	19/12/2020	Nature of Claim:	TP
		Claim No:	3987416679SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT8222B	Engine No:	12047954N52B30AF
Make & Model:	BMW 730LI, 3.0 (A)	Chassis No:	WBAKB22030C951378
Reg. Date:	27/02/2012 (Man. Year: 2011)	Odometer:	179746 km
Colour:	White		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R20	Rear Tyre Size:	245/40 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,787.23	1,740.73	46.50	2.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	755.00	555.00	200.00	26.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,542.23	2,295.73	246.50	9.70
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	2,542.23	1,800.00	742.23	29.20
+ GST 7.00/7.00% (S\$)	177.96	126.00	51.96	29.20
Nett Amount (S\$)	2,720.19	1,926.00	794.19	29.20
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
(S\$)		2,086.00		
Liabe Amount (50.00%) (S\$)		1,043.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,050.45		

INSPECTION

Date of Assignment: 23/12/2020

Date Inspected: 23/12/2020 Inspected At:

NPH Auto Service (HQ)
Blk 9005 Tampines Steet 93, #01-246/254
Singapore 528839

4/12/2021

Adjuster Report

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	28.40 FL	*28.40 FL
2	1		*FRONT BUMPER PARKING SENSOR RH	Cut	238.05 FL	*238.05 FL
3	1		*FRONT BUMPER CHROME RH	Not Necessary	48.95 FL	*. FL
4	1		*FRONT BUMPER	Deformed	1,565.90 FL	*1,565.90 FL
F=Franchise part. L=ListItemDisc.						
				Sub Total (S\$)	1,881.30	1,832.35
				- List Item Discount on L Items 5.00/5.00% (S\$)	94.07	91.62
				Total Parts (S\$)	1,787.23	1,740.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND INSTALL FRONT BUMPER ,FRONT HEADLAMP ,FRONT FOG LAMP L&R ,INDICATOR LAMP ,FRONT BUMPER CHROME L&R ,WIPER NOZZLE COVER ,TOWING HOOK COVER & PARKING SENSOR	New	350.00	250.00
2	SPRAY PAINTING	New	300.00	250.00
3	RENEW PARKING SENSOR AND SETTING	New	80.00	30.00
4	CHECK WIRING SYSTEM	New	25.00	25.00
Gross Labour Cost (S\$)			755.00	555.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >