



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6190C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	COVER REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
10	BUMPER PIECE	NOT NECESSARY	22.00	-
	LESS 25% DISCOUNT		-120.15	-
			360.45	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING (REPAIR RR FENDER RH).INCLUSIVE OF THE REPAIR OF COVER REAR BUMPER .		500.00	480.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
			1,030.00	910.00
<b>GRAND TOTAL</b>			<b>1,390.45</b>	<b>910.00</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>910.00</b>

Report Ref No. NS/INC21000019/T1vd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.