



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7706B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	IONIQVC COVER-RR BUMPER	CRACKED	459.40	459.40
1	IONIQV2-4 MOULDING ASSY-R	CRACKED	451.25	451.25
1	IONIQVC ANTENNA ASSY-SMAR	NOT NECESSARY	40.50	-
1	IONIQVC CAP-RR HOOK	NOT NECESSARY	98.80	-
1	IONIQVC BEAM-RR BUMPER	NOT NECESSARY	394.80	-
1	IONIQVC MOULDING-REAR BUM	CRACKED	155.00	155.00
1	IONIQVC COVER-RR BPR UNDE	NOT NECESSARY	225.00	-
	LESS 20% DISCOUNT		-364.95	-213.13
			1,459.80	852.52
<u>NETT ITEMS</u>				
1	NO PLATE (S)(N)	CRACKED	25.00	25.00
	LESS 10% DISCOUNT		-2.50	-2.50
			22.50	22.50
<u>LABOUR</u>				
	TOWING FEE.		60.00	-
	PANEL BEATING.		400.00	320.00
	SPRAYPAINT CHARGE.		300.00	200.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			840.00	550.00
GRAND TOTAL			2,322.30	1,425.02
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,425.02

Report Ref No. NS/INC21000020/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.