

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21000023/AQD3E2

**Date:** 02/03/2021

### REFERENCE

Insured/Claimant: TIAN WEI SIGNATURE PTE LTD Policy No: 2000001818  
Date of Loss: 30/12/2020 Nature of Claim: OD Claim No: 1259171339SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ1545L**  
Make & Model: NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A) Engine No: K9KE628D635253  
Reg. Date: 17/01/2019 (Man. Year: 2018) Chassis No: VSKYBAM20Z0174415  
Colour: Red Odometer: 80403 km  
Engine Capacity: 1461 cc  
Market Value/New Car Price: S\$52,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 175/70R14C Rear Tyre Size: 175/70R14C  
Front Left Side: Windforce 6 mm Rear Left Side: Windforce 6 mm  
Front Right Side: Windforce 6 mm Rear Right Side: Windforce 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25,753.53	12,862.35	12,891.18	50.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,620.00	2,410.00	6,210.00	72.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>34,373.53</b>	<b>15,272.35</b>	<b>19,101.18</b>	<b>55.57</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>33,573.53</b>	<b>14,472.35</b>	<b>19,101.18</b>	<b>56.89</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,350.15</b>	<b>1,013.06</b>	<b>1,337.09</b>	<b>56.89</b>
<b>Nett Amount (S\$)</b>	<b>35,923.68</b>	<b>15,485.41</b>	<b>20,438.27</b>	<b>56.89</b>

### INSPECTION

Date of Assignment: 03/01/2021

Date Inspected: 04/01/2021 Inspected At:

New Hock Teck Motor Workshop (HQ)  
Blk 1, Kaki Bukit Avenue 6 #01-43, AutoBay @  
Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 8.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,157.90 FL	*882.00 FL
2	2		*FRONT BONNET HINGE	Bent	115.40 FL	*115.40 FL
3	1		*FRONT BONNET LOCK	Damaged	78.70 FL	*78.70 FL
4	1		*FRONT BONNET INSULATION	Crumpled	286.50 FL	*286.50 FL
5	10		*FRONT BONNET INSULATION CLIP	Necessary	65.00 FL	*30.00 FL
6	2		*FRONT HEAD LAMP	Cracked	892.80 FL	*892.80 FL
7	2		*FRONT HEAD LAMP LOWER BRACKET	Not Necessary	151.40 FL	*- FL
8	1		*FRONT BUMPER	Distorted	589.70 FL	*589.70 FL
9	2		*FRONT BUMPER SIDE RETAINER	Necessary	70.40 FL	*70.40 FL
10	10		*FRONT BUMPER CLIP	Necessary	65.00 FL	*30.00 FL
11	2		*FRONT BUMPER TOP SIDE COVER	Missing	724.40 FL	*724.40 FL
12	1		*FRONT BUMPER CENTRE GARNISH	Not Necessary	231.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	614.90 FL	*614.90 FL
14	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	183.40 FL	*- FL
15	2		*FRONT BUMPER FOG LAMP	Not Necessary	371.00 FL	*- FL
16	1		*FRONT GRILLE	Cracked	338.00 FL	*338.00 FL
17	8		*FRONT GRILLE CLIP	Necessary	52.00 FL	*20.00 FL
18	1		*FRONT GRILLE EMBLEM LOGO	Necessary	73.50 FL	*73.50 FL
19	1		*FRONT GRILLE LOWER MOULDING	Not Necessary	205.50 FL	*- FL
20	1		*FRONT SUPPORT PANEL	Distorted	1,057.00 FL	*395.00 FL
21	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	145.30 FL	*- FL
22	1		*FRONT SUPPORT PANEL AIR DUCT COVER	Deformed	129.20 FL	*129.20 FL
23	1		*FRONT RADIATOR TANK	Cracked	94.60 FL	*94.60 FL
24	1		*FRONT WIPER GARNISH	Not Necessary	277.20 FL	*- FL
25	1		*FRONT FENDER	O/s Buckled	1,009.40 FL	*504.70 FL
26	2		*FRONT FENDER COWLING	Not Necessary	285.60 FL	*- FL
27	16		*FRONT FENDER COWLING CLIP	Not Necessary	104.00 FL	*- FL
28	1		*FRONT HORN (2PCS)	Damaged (1Pc Only)	197.60 FL	*98.80 FL
29	1		*FRONT BATTERY BRACKET	Not Necessary	127.10 FL	*- FL
30	1		*FRONT BATTERY TRAY	Not Necessary	38.20 FL	*- FL
31	1		*FRONT FUSE BOX (SMALL)	Not Necessary	197.10 FL	*- FL
32	1		*FRONT AIR CLEANER BOX ASSY	Cracked	566.40 FL	*455.00 FL
33	1		*FRONT ENGINE LOWER COVER	Not Necessary	272.30 FL	*- FL
34	2		*FRONT CHASSIS	Repair	1,485.20 FL	*- FL
35	1		*FRONT WIPER TANK	Deformed	247.90 F	*195.00 FN
36	1		*FRONT BATTERY	Not Necessary	155.00 F	*- FN
37	1		*FRONT FUSE BOX (SMALL)	Not Necessary	360.00 F	*- FN
38	1		*FRONT RADIATOR	Distorted	687.40 F	*687.40 FN
39	1		*FRONT RADIATOR FAN MOTOR	Cracked	685.90 F	*317.00 FN
40	1		*FRONT RADIATOR TANK	Repeated	186.90 F	*- FN
41	1		*FRONT AIR-CON CONDENSER	Distorted	653.00 F	*653.00 FN
42	1		*FRONT AIR-CON AIR DUCT BLOWER ASSY	Not Necessary	508.40 F	*- FN
43	1		*FRONT AIR-CON COOLANT COIL BLOWER ASSY	Not Necessary	1,101.40 F	*- FN
44	1		*FRONT FAN BELT	Not Necessary	43.40 F	*- FN
45	1		*FRONT ALTERNATOR	Cracked	1,889.80 F	*1,889.80 FN
46	1		*FRONT AIR-CON COMPRESSOR	Damaged	1,121.10 F	*1,121.10 FN
47	1		*FRONT AIR-CON COMPRESSOR PIPE	Not Necessary	251.30 F	*- FN
48	2		*FRONT AIR-CON COMPRESSOR BRACKET	Not Necessary	108.80 F	*- FN
49	1		*FRONT INTERCOOLER	Dented	2,121.60 F	*2,121.60 FN
50	1		*FRONT INTERCOOLER HOSE	Not Necessary	859.90 F	*- FN
51	3		*FRONT ENGINE MOUNTING	Not Necessary	203.50 F	*- FN
52	1		*FRONT COMPRESSOR	Repeated	1,656.30 F	*- FN
53	1		*FRONT FAN MOTOR RESISTOR RELAY	Not Necessary	335.60 F	*- FN
54	1		*FRONT FAN MOTOR RESISTOR RELAY BRACKET	Not Necessary	65.00 F	*- FN
55	1		*GUM	Not Necessary	50.00 F	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		<b>*FRONT AIR-CON SECTION PIPE</b> (Supplementary)	Bent	278.00 F	*278.00 FN
57	1		<b>*FRONT AIR-CON DISCHARGE PIPE</b> (Supplementary)	Bent	415.90 F	*335.00 FN
58	2		<b>*FRONT SUPPORT PANEL SIDE PANEL</b> (Supplementary)	Distorted	510.00 F	*270.00 FN
59	2		<b>*FRONT BUMPER FOG LAMP HOUSING</b> (Supplementary)	Not Necessary	230.00 F	*- FN

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>26,978.80</b>	<b>14,291.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,225.27	642.36
<b>- Nett Item Discount on N Items 0.00/10.00% (\$)</b>	0.00	786.79
<b>Total Parts (\$)</b>	<b>25,753.53</b>	<b>12,862.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT FRONT DASHBOARD	New	300.00	0.00
2	TO REMOVE & REFIT FRONT WINDSCREEN	New	120.00	0.00
3	TO REMOVE & REFIT AIR-CON BLOWER,COOLANT COIL,AIR DUCT BLOWER & TOP UP GAS	New	280.00	0.00
4	TO REMOVE & REFIT AIR-CON CONDENSER,RADIATOR,FAN MOTOR & TOP UP GAS	New	280.00	120.00
5	TO REMOVE & REFIT FRONT R/H DOOR,GLASS,GEAR MOTOR,LOCK,RUBBER & TRIM BOARD	New	180.00	0.00
6	TO REMOVE & REFIT FRONT ENGINE	New	550.00	0.00
7	TO REMOVE & REFIT FRONT UNDERCARRIAGE	New	280.00	0.00
8	TO REMOVE & REFIT FRONT STEERING RACK & CROSSMEMBER	New	380.00	0.00
9	TO REPAIR CHASSIS MEMBER	New	450.00	0.00
10	TO CHECK WIRING	New	100.00	30.00
11	TO CHECK WHEEL ALIGNMENT	New	150.00	0.00
12	TOWING FEE	New	150.00	60.00
13	PANEL BEATING	New	3,000.00	1,100.00
14	SPRAY PAINTING	New	2,400.00	1,100.00
			<b>Gross Labour Cost (\$)</b>	<b>8,620.00</b>
				<b>2,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >