

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21000026/EVD3E2

Date: 25/01/2021

REFERENCE

Insured/Claimant:	TAN HAN QI	Policy No:	1900117812	Claim No:	8866329523SG
Date of Loss:	30/12/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM6890K	Engine No:	3A92UHT5347
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH002063
Reg. Date:	10/07/2019 (Man. Year: 2019)	Odometer:	23032 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,707.55	5,879.52	1,828.03	23.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	3,190.00	2,190.00	40.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,087.55	9,069.52	4,018.03	30.70
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,487.55	8,469.52	4,018.03	32.18
+ GST 7.00/7.00% (S\$)	874.13	592.87	281.26	32.18
Nett Amount (S\$)	13,361.68	9,062.39	4,299.29	32.18

INSPECTION

Date of Assignment:	31/12/2020	
Date Inspected:	31/12/2020 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE, FR BUMPER	Broken	703.00 FL	*703.00 FL
2	5		*CLIP, FR BUMPER	Necessary	20.00 FL	*20.00 FL
3	1		*COVER, FR BUMPER	Not Necessary	12.00 FL	*- FL
4	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	62.00 FL	*- FL
5	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
6	1		*GRILLE, FR UNDER	Broken	165.00 FL	*165.00 FL
7	1		*BRACKET, FR BUMPER, LH	Broken	13.00 FL	*13.00 FL
8	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
9	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
10	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
11	1		*GRILLE, RADIATOR	Broken	554.00 FL	*554.00 FL
12	1		*HOOD	Dented	734.00 FL	*734.00 FL
13	1		*HINGE, HOOD, LH	Not Necessary	56.00 FL	*- FL
14	1		*HINGE, HOOD, RH	Not Necessary	56.00 FL	*- FL
15	8		*CLIP, HOOD INSULATOR	Necessary	24.00 FL	*24.00 FL
16	1		*LATCH, HOOD	Not Necessary	69.00 FL	*- FL
17	1		*PANEL ASSY, FR END	Dented	1,055.00 FL	*1,055.00 FL
18	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	65.00 FL	*- FL
19	1		*PANEL, AIR GUIDE, LH	Cracked	11.00 FL	*11.00 FL
20	1		*PANEL, AIR GUIDE, RH	Cracked	11.00 FL	*11.00 FL
21	1		*CONDENSER ASSY, A/C REFRIGE	Bent	758.00 FL	*758.00 FL
22	1		*PANEL, AIR GUIDE	Not Necessary	112.00 FL	*- FL
23	1		*RADIATOR ASSY	Not Necessary	967.00 FL	*- FL
24	1		*FAN, COOLING	Not Necessary	77.00 FL	*- FL
25	1		*SHROUD, COOLING FAN	Not Necessary	130.00 FL	*- FL
26	1		*MOTOR, COOLING FAN	Not Necessary	479.00 FL	*- FL
27	1		*HEADLAMP ASSY, LH	Cut	660.00 FL	*660.00 FL
28	1		*HEADLAMP ASSY, RH	Broken	660.00 FL	*660.00 FL
29	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
30	1		*LLC 4L	Necessary	26.00 FL	*26.00 FL
31	1		*EMBLEM ECO	Not Necessary	17.00 FS	*- FS
32	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,505.00	7,139.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,797.45	1,259.48
Total Parts (S\$)	7,707.55	5,879.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT BUMPER BODY KIT, BONNET & FRT SUPPORT. REPAIR LHF FENDER & RHF FENDER	New	2,700.00	1,350.00
2	RESPRAY FRT BUMPER, FRT BUMPER BODY KIT, BONNET, FRT SUPPORT, LHF FENDER & RHF FENDER	New	2,100.00	1,400.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
8	SUPPLY BODY KIT SEALANT	New	80.00	60.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			5,380.00	3,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >