

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 1977014696

: 1977014696	ESTIMATE	GST Reg No : MR-8500111-				
Invoice Name & Address		Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Date In/Mileage Chassis No Engine No	KCV11692/Mr Tan Han Qi SMM6890K*DC17/ 10/07/201 / 23032 MMBSTA13AKH002063 3A92UHT5347 MIT/19MY ATTRAGE 1.2 CVT U01 TITANIUM GREY M/ BK BLACK				

Account No. Torme Date/Time Printed CSE Operato		WIP No			
Account No Terms Date/Time Finned	dwin Caina	61336			
AAUUUUI (Pegit 31/12/2020) 00:34 403	Qty	Unit Price	Disc%	Ar	nount
Description of Goods / Services E PNT88000 , RENEW FRT BUMPER , FRT BUMPER BODY KIT , BONNET & FRT SU	PPORT 450 / 3		1350	950	2700.00
REPAIR LHF FENDER & RHF FENDER E PNT98000 RESPRAY FRT BUMPER , FRT BUMPER BODY KIT , BONNET , FRT			1490	1250	2100.00
LHF FENDER & RHF FENDER E PNT88000				7	100.00
REMOVE & REFIT AC COND & RADIATOR				1 3	80.00
TOP UP AIRCON GAS	~ Д ~	, ,			30.0
CHECK WIRING ELECTRICAL SYSTEM & ADVOST HEADTIAME ATM 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING THE SCAN PRO TEST	nate				120.0
USING HI-SCAN PRO TEST SUNDRY					50.0
SUPPLY FRT NUMBER PLATE WITH CASING SUNDRY				60	80.0
SUPPLY BODY KIT SEALANT SUNDRY					120.0
APPLY ANTI CORROSION ON AFFECTED AREAS SUNDRY				20	30.0
Sundries FACE, FR BUMPER / DR	1.00		23.00		541.3 15.4
CLIP, FR BUMPER (The (OL)) X N/N COVER, FR BUMPER (The (OL))	5.00 1.00	12.00	23.00		9.2
COVER, HEADLAMP SUPT PANEL () ///)	1.00	69.00	23.00		53.1 127.0
GRILLE, FR UNDER UK	1.00	13.00	23.00	1	10.0
BRACKET, FR BUMPER, RH	1.00	127.00	23.00 23.00 23.00		97. 97.
GARNISH, FR BUMPER, RH X N/11	1.00	127.00	23.00		37.1

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 1977(01469G	ESTIMATE	GST Reg No : MR-8500111-X
	Invoice Name & Address		Owner Name & Vehicle Info
Ltd. MOTO 78 S AIG SING	Asia Pacific Insurance Pte. R CLAIM DEPARTMENT HENTON WAY #08-16 BUILDING APORE 079120 act No 6419 1000	Reg No/Reg Date Date In/Mileage Chassis No Engine No	KCV11692/Mr Tan Han Qi SMM6890K*DC17/ 10/07/201 / 23032 MMBSTA13AKH002063 3A92UHT5347 MIT/19MY ATTRAGE 1.2 CVT UO1 TITANIUM GREY M/ BK BLACK

Terms	Data Timo Drinton								
	Date/Time Printed	CSE	Operator 261 / Edwin Co	aina		61336			
Credit	31/12/2020/ 08:54	QUE	201 / LUMIN C		ty U	nit Price		- /	Amount
	Description of Goods	/ Services	A SUR PER SUR PROPERTY OF THE PROPERTY OF			554.00	23.00		426.
DIATOR	/ UK					734.00	23.00		565.
00				1.	00	56.00	23.00		43.
D, LH X				1.	00				43.
D,RH ^	1910					3.00	23.00		18.
INSULAT				1.	00	69.00	23.00	,	53
O X N	M 1 JAKA dented					1055.00	23.00	/	812 50
Y, FR END	TANT AND			1.	00	65.00	23.00	/	8
DLAMP SU	PPURA, UPN A PA					11.00	23.00	/	
GUIDE, LI	1 - 1 - 1 - 1 - 1	_		1.	00			1	8.
GUIDE, RI	DEEDICE T	0		Γ 1.	00	758.00	23.00		583 86
ASSY,A/C	VCI VIOL	\sim 7 P P	TOO G	少代 知	99	112.00	23.00		744
00.00		\approx 1 Γ 11	10012	 	00-1	967.00	23.00		
357) (디I	(c	الى <u>ال</u>	00				59
16 × 1	IN AIRI			1.	00				100
LING FAN	V AILI			1.	00	479.00	23.00		368
ING FAN	CUI			1.	00	660.00	23.00	/,	508
				1.	00	660.00	23.00	//	508
SSY, KH	00			1.	00	1643.00	20.00	//	1314.
RODAKTIZ				1.0	00	26.00	23.00	/	20.
2				1.0	00	17.00	00.00		17.
X	LIM								
•				14					
	90° _E	Hove (1	(K) $2(1)$	2/29 . [[.	1000		- 1		
	CHRITEYOR NAME .	les CCI	יון יט עיי	1, 1,.,	100				
	SURVETOR WANTE	on	- Mal Al				- 1		
	SURVEYOR SIGNATURE	:	MIT HU						
		EX	cess - 1				1		
	DATE:						- 1		
		C B	dus				2 2		
	REMARKS:	0/0					- 1		
		#/#					- 1	13	,087.5
	Mary Conference Confer	A 1							
		101 131	Sha						
epted by	e notify	,	99			No++		1	2,758.9
			* 37 3x 27 160 16 160 J E	71. 007	·			•	893.1
,	-			7% GS1	on	12/30.93	5		
					Total	Payahle	0	1	3,652.0
					IULAI	rayabie			
s on a "Witho	ut Prejudice" basis								
	INSULATION AND INSULATION AND INSULATION AND INSULATION AND INSULATION ASSY, A/O GUIDE, INSULATION ASSY, LH SOLING FAN ING FAN	DIATOR UK DIATOR UK DIATOR UK DIATOR VICTOR DIATOR X NAI INSULATOR V, FR END DIAMP SUPPORT, UPR GUIDE, LH GUIDE, LH ASSY, A/C REFRIGE GUIDE GUIDE SURVEYOR NAME: SURVEYOR SIGNATURE	DOUBLE SHALL STORY SURVEYOR NAME: SURVEYOR SIGNATURE: DATE: REMARKS: RE	ADIATOR ADIATOR ADIATOR ADIATOR ADIATOR ADIATOR ADIATOR ADIA ADI	Description of Goods / Services 1. DIATOR	Description of Goods / Services 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.	Description of Goods / Services 1.00 554.00 1.00 734.00 1.00 734.00 1.00 734.00 1.00 56.00 1.00 56.00 1.00 56.00 1.00 56.00 1.00 69.00 1.00 69.00 1.00 69.00 1.00 1.00 69.00 1.00	Description of Goods / Services 1.00 554.00 23.00 DIDIATOR	Description of Goods / Services 1.00 554.00 23.00 1.00 734.00 23.00 1.00 734.00 23.00 1.00 56.00 23.00 1.00 56.00 23.00 1.00 56.00 23.00 1.00 66.00 23.0

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubher seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen. Page 2 of 2