

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21000028/KVD3E2

**Date:** 15/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100463880  
Claimant Vehicle No : SBS8298G Insured Vehicle No : SDX899A  
Date of Loss: 27/12/2020 Nature of Claim: TP Claim No: 8296057516SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS8298G**  
Make & Model: SCANIA KUB4X2, 8.9 ABS TURBO 2WD (A) Engine No: 6384730  
Reg. Date: 08/08/2008 (Man. Year: 2008) Chassis No: YS2K4X20001861374  
Colour: Multi-colour Odometer: 1029948 km  
Engine Capacity: 8867 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	266.00	266.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	914.40	0.00	914.40	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,180.40</b>	<b>266.00</b>	<b>914.40</b>	<b>77.47</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>82.63</b>	<b>18.62</b>	<b>64.01</b>	<b>77.47</b>
<b>Nett Amount (S\$)</b>	<b>1,263.03</b>	<b>284.62</b>	<b>978.41</b>	<b>77.47</b>

### INSPECTION

Date of Assignment: 03/01/2020  
Date Inspected: 04/01/2021 Inspected At: SBS Transit Ltd (AMK)  
15 Ang Mo Kio Street 63  
Singapore 569117  
Estimated Period of Repair: 1.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP COVER O/S;F/GLASS;B	Cracked	250.00 FS	*250.00 FS
2	2		*PURPLE PAINT	Necessary	16.00 FS	*16.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					266.00	266.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WORKSHOP LABOUR	New	192.00	0.00
2	CONTRACTORS REPAIR CHARGES	New	450.00	0.00
3	OVERHEADS	New	272.40	0.00
<b>Gross Labour Cost (S\$)</b>			<b>914.40</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >