

Certification for Bus Repairs

SBS Transit

CBR REF NO. : AM20205584

Depot : AM

Report No.: E53412020

BUS VEHICLE NO. : SBS8298G

Driver's Co no. & Name : 18215 Siang Chee Choy

Accident Date : 27/12/2020

Date in : 30/12/2020

Date Out : 04/01/2021

Yr Of Reg	Make / Model	Chassis No.
2008	Scania KUB4X2, SD, AC, 2 Axle	YS2K4X20001861374

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30122010	HEADLAMP COVER O/S;F/GLASS; B	1	<i>CM</i> \$250.00 ✓
99002064	PURPLE PAINT	2	<i>m</i> \$16.00 ✓
TOTAL FOR PARTS			S\$ 266.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	192.00
2	Contractor's repair charges	S\$	450.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 642.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 908.00

Certification for Bus Repairs



CBR REF NO. : AM20205584

Depot : AM

Report No.: E53412020

BUS VEHICLE NO. : SBS8298G

Driver's Co no. & Name : 18215 Sjang Chee Choy

Accident Date : 27/12/2020

Date in : 30/12/2020

Date Out : 04/01/2021

Yr Of Reg	Make / Model	Chassis No.
2008	Scania KUB4X2, SD, AC, 2 Axle	YS2K4X20001861374
TOTAL DAMAGE		S\$ 908.00
Overheads		<i>M</i> S\$ 272.40
Towing Charges		S\$ -
Repair Period : 1 day(s)	Loss of Use	S\$ 356.29
TOTAL LOSS		S\$ 1536.69

Prepared By : Li Ming

Date : 07/01/2021

Approved By

Workshop Mgr : Wong Yew Fatt

Date : 07/01/2021

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 1536.69

Acknowledged By

Depot Safety : Chang Su Peng

Date : 07/01/2021

* This is computer generated document and does not require signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: