

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21000032/ETD3E2

**Date:** 02/02/2021

### REFERENCE

Insured/Claimant:	JUSTIN BLAZE S/O GEORGE	Policy No:	1800020683	
Date of Loss:	20/12/2020	Nature of Claim:	OD	Claim No: 9061198917SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW8483Z		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11XN8735
Reg. Date:	06/03/2018 (Man. Year: 2017)	Chassis No:	GF7W0401220
Colour:	Brown	Odometer:	71295 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$89,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,537.66	1,527.66	10.00	0.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,460.00	2,190.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,187.66</b>	<b>2,987.66</b>	<b>2,200.00</b>	<b>42.41</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	4,587.66	2,387.66	2,200.00	47.95
<b>+ GST 7.00/7.00% (S\$)</b>	321.14	167.14	154.00	47.95
<b>Nett Amount (S\$)</b>	<b>4,908.80</b>	<b>2,554.80</b>	<b>2,354.00</b>	<b>47.95</b>

### INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 04/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*PANEL ASSY, RR DOOR, LH	Dented	937.00 FL	*937.00 FL
3	1		*GARNISH, RR DOOR, LH	Cut	164.00 FL	*164.00 FL
4	1		*AIR DAM, SIDE, LH	Cut	541.00 FL	*541.00 FL
5	1		*TAPE, RR DOOR SASH	Necessary	42.00 FL	*42.00 FL
6	1		*TAPE, RR DOOR SASH	Necessary	42.00 FL	*42.00 FL
7	1		*MOULDING, RR WHEEL ARCH, LH	Cut	199.00 FL	*199.00 FL
8	1		*W/STRIP, R/DR OPN, LWR OTR L (Supplementary)	Torn	33.00 FL	*33.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,988.00	1,978.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	450.34	450.34
Total Parts (\$\$)	1,537.66	1,527.66

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW LHR DOOR. REPAIR LHR FENDER	New	2,250.00	450.00
2	RESPRAY LHR DOOR, LHR FENDER & LH ROCKER PNL	New	1,050.00	700.00
3	REMOVE & REFIT LHR DOOR COMPONENT	New	120.00	120.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,650.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >