

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000034/ETD3Q2

Date: 28/01/2021

REFERENCE

Insured/Claimant:	LIU WEILIANG, RYAN	Policy No:	1800147027	
Date of Loss:	01/01/2021	Nature of Claim:	OD	Claim No: 1766160569SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG8453H			
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGJH713022	
Reg. Date:	02/01/2019 (Man. Year: 2018)	Chassis No:	KNAF3416MK5023976	
Colour:	Red	Odometer:	49808 km	
Engine Capacity:	1591 cc			
Market Value/New Car Price:	S\$69,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 4 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,456.80	2,217.60	1,239.20	35.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,560.00	3,130.00	2,430.00	43.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,016.80	5,347.60	3,669.20	40.69
+ GST 7.00/7.00% (S\$)	631.18	374.33	256.85	40.69
Nett Amount (S\$)	9,647.98	5,721.93	3,926.05	40.69

INSPECTION

Date of Assignment:	04/01/2021	
Date Inspected:	04/01/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
2	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
3	1		*COVER-RR BUMPER FOG LAMP,RH	Not Necessary	19.00 FL	*- FL
4	1		*LAMP ASSY-SIDE T/SIGNAL,RH	Not Necessary	181.00 FL	*- FL
5	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
6	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
7	1		*STAY-RR BUMPER,LH	Bent	65.00 FL	*65.00 FL
8	1		*STAY-RR BUMPER,RH	bent	65.00 FL	*65.00 FL
9	1		*BRACKET ASSY-RR BPR SIDE UPR,L	Not Necessary	25.00 FL	*- FL
10	1		*BRACKET ASSY-RR BPR SIDE UPR,R	Not Necessary	31.00 FL	*- FL
11	1		*PANEL ASSY-BACK	Not Necessary	324.00 FL	*- FL
12	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 FL	*- FL
13	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
14	1		*HINGE ASSY-TRUNK LID,LH	Not Necessary	97.00 FL	*- FL
15	1		*HINGE ASSY-TRUNK LID,RH	Not Necessary	97.00 FL	*- FL
16	1		*W/STRIP-TRUNK LID OPNG	Not Necessary	100.00 FL	*- FL
17	1		*LATCH ASSY-TRUNK LID	Not Necessary	112.00 FL	*- FL
18	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FL	*- FL
19	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
20	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
21	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
22	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
23	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,251.00	2,757.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	794.20	539.40
Total Parts (\$\$)	3,456.80	2,217.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW RR BUMPER,BOOTLID & RR END PNL.REPAIR RR FLR PNL,LHR FENDER & RHR FENDER	New	2,000.00	800.00
2	RESPRAY RR BUMPER,RR END PNL,BOOTLID,RR FLR PNL,LHR FENDER & RHR FENDER	New	2,100.00	960.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD,TRIM & CARPET *Check	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00
8	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
10	REPAIR REAR END PANEL SUPPLEMENTARY	New	400.00	400.00
11	RESPRAY ON REAR END PANEL SUPPLEMENTARY	New	480.00	480.00
Gross Labour Cost (\$\$)			5,560.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >