

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000040/ETD3E2

Date: 03/02/2021

REFERENCE

Insured/Claimant:	SUZANA BTE ABDUL RAHIM	Policy No:	1900247510	
Date of Loss:	01/01/2021	Nature of Claim:	OD	Claim No: 8065141310SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ6242K	Engine No:	3A92UJB2056
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH003433
Reg. Date:	27/11/2019 (Man. Year: 2019)	Odometer:	10948 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,839.51	4,749.99	1,089.52	18.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	4,915.00	1,065.00	17.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,819.51	9,664.99	2,154.52	18.23
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	11,219.51	9,064.99	2,154.52	19.20
+ GST 7.00/7.00% (S\$)	785.37	634.55	150.82	19.20
Nett Amount (S\$)	12,004.88	9,699.54	2,305.34	19.20

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 04/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,RH	Broken	660.00 FL	*660.00 FL
2	1		*LAMP ASSY,FOG,FR LH	Not Necessary	303.00 FL	*- FL
3	1		*FACE,FR BUMPER	Broken	703.00 FL	*703.00 FL
4	1		*MARK,THREE-DIA	Not Necessary	69.00 FL	*- FL
5	1		*GRILLE,FR UNDER	Not Necessary	165.00 FL	*- FL
6	1		*AIR DAM,SIDE,FR RH	Not Necessary	18.00 FL	*- FL
7	1		*BRACKET,FR BUMPER,RH	Broken	13.00 FL	*13.00 FL
8	1		*GARNISH,FR BUMPER,RH	Cut	127.00 FL	*127.00 FL
9	1		*HOOD	Dented	734.00 FL	*734.00 FL
10	1		*HINGE,HOOD,RH	Not Necessary	56.00 FL	*- FL
11	1		*HINGE,HOOD,LH	Not Necessary	56.00 FL	*- FL
12	1		*FENDER,FR RH	Dented	497.00 FL	*497.00 FL
13	1		*REINFORCEMENT,FR BUMPER	Not Necessary	466.00 FL	*- FL
14	1		*SHIELD,FR WHEELHOUSE,RH	Torn	98.00 FL	*98.00 FL
15	1		*COVER,DOOR MIRROR,OTR RH	Repair	114.00 FL	*- FL
16	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
17	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
18	1		*LAMP ASSY,SIDE T/SIG,FR RH	Not Necessary	129.00 FL	*- FL
19	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
20	1		*PANEL ASSY, FR END (Supplementary)	Dented	1,055.00 FL	*1,055.00 FL
21	1		*TANK, WINDSHIELD WASHER (Supplementary)	Crushed	74.00 FL	*74.00 FL
22	1		*LLC 4L (Supplementary)	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,073.00	5,667.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,233.49	917.01
Total Parts (\$\$)	5,839.51	4,749.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,BONNET,FRT RH FENDER & AFFECTED AREA.REPAIR ON FRT RH WHEEL HOUSING	New	2,250.00	1,575.00
2	PAINT WORK ON FRT BUMPER,BONNET,FRT RH FENDER,FRT RH WHEEL HOUSING,FRT RH DOOR,BODY KIT & RH WING MIRROR COVER	New	2,450.00	2,180.00
3	PERFORM RUST PREVENTION	New	80.00	40.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	400.00	320.00
7	VACUUM & TOP AIRCON GASE (Supplementary)	New	80.00	80.00
8	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
9	REMOVE & INSTALL RADIATOR AND AIRCON CONDENSER (Supplementary)	New	120.00	120.00
Gross Labour Cost (S\$)			5,980.00	4,915.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >