

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000041/EVD3Q2

Date: 08/02/2021

REFERENCE

Insured/Claimant:	Eu Teik Leong	Policy No:	2100421910	
Date of Loss:	27/12/2020	Nature of Claim:	OD	Claim No: 6813439729SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU3418T		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGFH776547
Reg. Date:	21/07/2015 (Man. Year: 2015)	Chassis No:	KNAFX411MF5448649
Colour:	Blue	Odometer:	70673 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$45,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,874.80	5,635.20	1,239.60	18.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	2,300.00	800.00	25.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,974.80	7,935.20	2,039.60	20.45
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	9,674.80	7,635.20	2,039.60	21.08
+ GST 7.00/7.00% (S\$)	677.24	534.46	142.78	21.08
Nett Amount (S\$)	10,352.04	8,169.66	2,182.38	21.08

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 04/01/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,RH	Broken	1,870.00 FL	*1,870.00 FL
2	1		*LAMP ASSY-HEAD,LH	Broken	1,870.00 FL	*1,870.00 FL
3	1		*CARRIER ASSY-FRONT END MODULE	Broken	776.00 FL	*776.00 FL
4	1		*RADIATOR ASSY	Not Necessary	546.00 FL	*- FL
5	1		*BLOWER ASSY	Not Necessary	606.00 FL	*- FL
6	1		*GUARD-AIR,RH	Not Necessary	19.00 FL	*- FL
7	1		*GUARD-AIR,LH	Not Necessary	19.00 FL	*- FL
8	1		*COVER-FR BUMPER	Broken	728.00 FL	*728.00 FL
9	1		*GRILLE ASSY-RADIATOR	Broken	322.00 FL	*322.00 FL
10	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	21.00 FL	*21.00 FL
11	1		*LIP ASSY-FRONT BUMPER	Not Necessary	54.00 FL	*- FL
12	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	33.00 FL	*- FL
13	1		*GARNISH-RADIATOR GRILLE,UPR	Broken	48.00 FL	*48.00 FL
14	1		*MOULDING-FRONT BUMPER A/INTAKE	Not Necessary	104.00 FL	*- FL
15	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	97.00 FL	*97.00 FL
16	1		*STIFFNER-FR BPR LWR	Not Necessary	131.00 FL	*- FL
17	1		*RAIL ASSY-FR BUMPER	Bent	410.00 FL	*410.00 FL
18	1		*BRACKET-FR BUMPER SIDE MTG,LH	Broken	13.00 FL	*13.00 FL
19	1		*BRACKET-FR BUMPER SIDE MTG,RH	Broken	13.00 FL	*13.00 FL
20	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FL	*51.00 FL
21	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
22	1		*CONDENSER ASSY-KIA SUB (Supplementary)	Bent	774.00 FL	*774.00 FL
23	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,581.00	7,039.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,706.20	1,403.80
Total Parts (\$)	6,874.80	5,635.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,SUPPORT PANEL & AFFECTED AREA	New	1,200.00	400.00
2	PAINT WORK ON FRT BUMPER PANEL	New	350.00	350.00
3	REMOVE & INSTALL RADIATOR,CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	TO SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
8	REPAIR RH FRONT FENDER & REPLACE SUPPORT PANEL (Supplementary)	New	800.00	800.00
9	SPRAY PAINT RH FRONT FENDER (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			3,100.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >