

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21000047/UVD3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SLH2491T

Insured Vehicle No : GBH8518E

Date of Loss: 03/01/2021

Nature of Claim:

TP

Claim No: CDMCG21000004

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH2491T**

Make & Model: CHEVROLET SONIC NB, 1.4 2WD (A)

Engine No: A14XER153030328

Reg. Date: 27/10/2016 (Man. Year: 2015)

Chassis No: KL1TA69FJGB558702

Colour: Orange

Odometer: 92452 km

Engine Capacity: 1398 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size:

205/55R16

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,290.90	5,638.00	4,652.90	45.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	2,510.00	1,510.00	37.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,310.90	8,148.00	6,162.90	43.06
Approved Total (Overridden) (\$\$)		6,500.00		
Nett Amount (\$\$)	14,310.90	6,500.00	7,810.90	54.58

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 05/01/2021 Inspected At:

Zoom Autowerkz Pte Ltd (HQ)

Blk 15 Kaki Bukit Road 4, #01-53

Bartley Biz Centre

Singapore 417808

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2021)
Parts:	143	CHEVROLET SONIC NB 1.4 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH2491T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID PANEL	Buckled	1,186.00 FL	*1,186.00 FL
2	1		*BOOTLID INNER TRIM GARNISH	Not Necessary	356.00 FL	*- FL
3	1		*SET BOOTLID INNER TRIM GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
4	1		*BOOTLID HINGE	N/s Twisted	156.00 FL	*78.00 FL
5	1		*BOOTLID CENTRE GARNISH	Cracked	278.00 FL	*260.00 FL
6	1		*BOOTLID LOGO	Necessary	115.00 FL	*115.00 FL
7	1		*BOOTLID EMBLEM (CHEVROLET)	Necessary	97.00 FL	*97.00 FL
8	1		*BOOTLID EMBLEM (SONIC)	Necessary	86.00 FL	*86.00 FL
9	1		*BOOTLID EMBLEM (LTZ)	Necessary	64.00 FL	*64.00 FL
10	1		*BOOTLID INNER LOCK	Twisted	295.00 FL	*166.00 FL
11	1		*BOOTLID LOCK SENSOR	Not Necessary	245.00 FL	*- FL
12	1		*BOOTLID WEATHER STRIP	Twisted	284.00 FL	*284.00 FL
13	2		*TAILLAMPS	O/s Cracked/N/s Broken	1,640.00 FL	*1,120.00 FL
14	1		*REAR BUMPER	Distorted	876.00 FL	*620.00 FL
15	1		*REAR BUMPER SIDE RETAINER	N/s Bent	156.00 FL	*60.00 FL
16	1		*REAR BUMPER BRACKET	N/s Cracked	144.00 FL	*72.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Not fitted	370.00 FL	*- FL
18	1		*REAR BUMPER SPONGE	Torn	145.00 FL	*145.00 FL
19	1		*SET REAR BUMPER CLIP	Necessary	60.00 FL	*60.00 FL
20	1		*REAR FENDER INNER SHIELD	N/s Twisted	388.00 FL	*112.00 FL
21	1		*REAR FENDER INNER TRIM GARNISH	N/s Torn	640.00 FL	*320.00 FL
22	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
23	1		*REAR SPARE TYRE TOP GARNISH	Not Necessary	311.00 FL	*- FL
24	1		*REAR SPARE TYRE PANEL	Repair	1,128.00 FL	*- FL
25	1		*REAR END PANEL	Badly Dented	986.00 FL	*850.00 FL
26	1		*REAR END PANEL TOP GARNISH	Cracked	275.00 FL	*225.00 FL
27	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
28	1		*BOOTLID SEALANT	Not Necessary	60.00 FS	*- FS
29	1		*REAR PARKING SENSOR	Shorted	250.00 FS	*200.00 FS
30	1		*REAR NUMBER PLATE W/GARNISH & SEAL	Necessary	60.00 FS	*60.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*50.00 FS
32	1		*REAR SPARE TRYE PANEL INSULATOR (ACCESSORIES)	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,331.00	6,230.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,040.10	592.00
Total Parts (\$\$)	10,290.90	5,638.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	980.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS (REAR BUMPER,END PANEL,BOOTLID,FENDERS,SPARE TYRE PANEL)	New	1,500.00	1,200.00
3	TO PROVIDE 2 TRIPS TO LTA TO REMOVE & INSTALL WEEKEND PLATES	New	250.00	50.00
4	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
5	TO REMOVE & INSTALL REAR BOOT TRIM,GARNISH	New	200.00	80.00
6	TO REMOVE & INSTALL REAR BOOT INTERIOR COMPONENTS	New	200.00	60.00
7	TO REMOVE & INSTALL,ALIGN REVERSE SENSOR	New	120.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	150.00	60.00
Gross Labour Cost (\$\$)			4,020.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >