

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21000049/ETD3E2

**Date:** 25/01/2021

### REFERENCE

Insured/Claimant:	TAN SENG YIAU	Policy No:	1900150058		
Date of Loss:	30/12/2020	Nature of Claim:	OD	Claim No:	4733894585SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN5692S		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGKH744185
Reg. Date:	19/08/2019 (Man. Year: 2019)	Chassis No:	KNAF1416MK5049768
Colour:	Grey	Odometer:	14183 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	64.80	64.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,380.00	2,430.00	63.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,874.80</b>	<b>1,444.80</b>	<b>2,430.00</b>	<b>62.71</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	3,274.80	844.80	2,430.00	74.20
<b>+ GST 7.00/7.00% (S\$)</b>	229.24	59.14	170.10	74.20
<b>Nett Amount (S\$)</b>	<b>3,504.04</b>	<b>903.94</b>	<b>2,600.10</b>	<b>74.20</b>

### INSPECTION

Date of Assignment:	03/01/2021		
Date Inspected:	06/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*MOULDING-WINDSHIELD GLASS	Necessary	56.00 FL	*56.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					76.00	76.00
- List Item Discount on L Items 20.00/20.00% (S\$)					11.20	11.20
Total Parts (S\$)					64.80	64.80

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPAIR ROOF PNL	New	2,000.00	400.00
2	RESPRAY ROOF PNL	New	1,100.00	350.00
3	REMOVE & REFIT ROOF LINING	New	200.00	120.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
7	SUPPLY FRT WINDSCREEN SEALANT	New	80.00	80.00
8	REMOVE & REFIT FRT WINDSCREEN GLASS	New	240.00	240.00
<b>Gross Labour Cost (S\$)</b>			<b>3,810.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >