

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21000064/QQD3E2
Date: 03/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100479049
Claimant Vehicle No : SG1126C **Insured Vehicle No :** SLF2130X
Date of Loss: 23/12/2020 Nature of Claim: TP Claim No: 4188170714SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG1126C**
Make & Model: MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A) Engine No: 902926C1101917
Reg. Date: 31/08/2016 (Man. Year: 2015) Chassis No: WEB62808323130036
Colour: Multi-colour Odometer: 324068 km
Engine Capacity: 6374 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35.00	35.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,192.00	2,000.00	192.00	8.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,227.00	2,035.00	192.00	8.62
+ GST 7.00/7.00% (S\$)	155.89	142.45	13.44	8.62
Nett Amount (S\$)	2,382.89	2,177.45	205.44	8.62

INSPECTION

Date of Assignment: 04/01/2021
Date Inspected: 05/01/2021 Inspected At: SBS Transit Ltd (YCK)
3 Yio Chu Kang Crescent
Singapore 786010
Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PUTTY KANDLE 2.5L	Necessary	35.00 FS	*35.00 FS
					Total Parts (\$)	35.00
						35.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY 3 WORKERS FOR 3 DAYS WORK }	New	1,100.00	1,100.00
2	-REPAIR LEFT SIDE PANEL NO.2, 3 & 4 }	New	0.00	0.00
3	-REPAIR LEFT SIDE DOOR NO.5 }	New	0.00	0.00
4	-SPRAY PAINTING LEFT SIDE PANEL NO.2, 3 & 4 }	New	0.00	0.00
5	-SPRAY PAINTING LEFT SIDE DOOR NO.5 }	New	0.00	0.00
6	-POLISH LEFT SIDE PANEL NO.1 }	New	0.00	0.00
7	-POLISH EXIT DOOR }	New	0.00	0.00
8	WORKSHOP ADMIN COST	New	192.00	0.00
9	LIVERY / ADVERTISEMENT COST	New	900.00	900.00
10	TOWING COST (NPA)	New	0.00	0.00
			Gross Labour Cost (\$\$)	2,192.00
				2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >