

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000065/UQD3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001287724

Claimant
Vehicle No : SCR8706P

Insured Vehicle No : PA4019B

Date of Loss: 29/12/2020

Nature of Claim: TP

Claim No: 251556

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCR8706P**

Make & Model: TOYOTA VIOS, 1.5 E (M)

Engine No: 1NZX459233

Reg. Date: 07/08/2006 (Man. Year: 2006)

Chassis No: MR053HY4204198415

Colour: Black

Odometer: 164699 km

Engine Capacity: 1497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 ZR16

Rear Tyre Size:

205/45 ZR16

Front Left Side: Nexen 6 mm

Rear Left Side:

Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side:

Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,520.62	1,410.78	3,109.84	68.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,460.00	1,170.00	44.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,150.62	2,870.78	4,279.84	59.85
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	7,150.62	2,200.00	4,950.62	69.23
+ GST 7.00/7.00% (S\$)	500.54	154.00	346.54	69.23
Nett Amount (S\$)	7,651.16	2,354.00	5,297.16	69.23

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 05/01/2021 Inspected At:

Tick Hai Motor & Welding Services -
Kaki Bukit (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-54
AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2021)
Parts:	143	TOYOTA VIOS 1.5 E (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCR8706P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed/Warped	332.40 FL	*295.10 FL
2	1		*SET REAR BUMPER CLIP	Necessary	12.80 FL	*12.80 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	22.40 FL	*- FL
4	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	12.40 FL	*- FL
5	1		*REAR FENDER RH	Repair	853.60 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Not Necessary	121.50 FL	*- FL
7	1		*REAR DOOR RH	Badly Dented	856.20 FL	*705.10 FL
8	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	48.15 FL	*- FL
9	1		*REAR DOOR OUTER HANDLE SMALL	Not Necessary	38.25 FL	*- FL
10	1		*REAR DOOR LOWER PROTECTOR RH	Bent	86.70 FL	*86.70 FL
11	1		*REAR DOOR WINDOW LOWER BLACK MOULDING RH	Not Necessary	78.20 FL	*- FL
12	1		*REAR DOOR INNER LOCK RH	Jammed/Shorted	219.40 FL	*219.40 FL
13	1		*REAR DOOR REGULATOR RH	Bent/Jammed	109.14 FL	*109.14 FL
14	1		*REAR DOOR INNER TRIMBOARD RH	Torn	858.60 FL	*366.10 FL
15	2		*REAR DOOR HINGE RH	Not Necessary	94.24 FL	*- FL
16	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	62.40 FL	*- FL
17	1		*FRONT DOOR RH	Repair	856.20 FL	*- FL
18	1		*FRONT DOOR OUTER HANDLE KEY LOCK RH	Not Necessary	48.15 FL	*- FL
19	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	48.15 FL	*- FL
20	1		*FRONT DOOR LOWER PROTECTOR RH	Bent	86.70 FL	*86.70 FL
21	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	62.40 FL	*- FL
22	1		*FRONT DOOR INNER LOCK RH	Not Necessary	272.85 FL	*- FL
23	1		*SIDE SKIRT RH	Repair	260.00 FL	*- FL
24	1		*REAR TYRE RIM RH	Repair	220.00 FS	*- FS
25	1		*WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
26	1		*WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
27	1		*FENDER SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,880.83	1,881.04
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,360.21	470.26
Total Parts (\$\$)	4,520.62	1,410.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL WIRING SYSTEM	New	80.00	20.00
2	TO REMOVE & REINSTALL INTERIOR TRIMS,GARNISHES ETC TO FACILITATE REPAIR	New	300.00	80.00
3	TO REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER RHR DOOR COMPONENT PARTS TO NEW DOOR	New	150.00	60.00
5	TO TRANSFER RHF DOOR COMPONENT PARTS TO NEW DOOR	New	150.00	0.00
6	TO REMOVE & REINSTALL REVERSE SENSOR	New	50.00	0.00
7	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING	New	800.00	550.00
8	TO PUTTY AND RESPRAY AFFECTED AREAS	New	950.00	750.00
Gross Labour Cost (\$\$)			2,630.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >