

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21000067/UQD3Q2

**Date:** 02/03/2021

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNW00123092000		
<b>Claimant Vehicle No :</b> SJW2711D	<b>Insured Vehicle No :</b> GBF5805G		
Date of Loss: 31/12/2020	Nature of Claim: TP	Claim No:	SNM21D200010/C02/TANKL

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJW2711D</b>	Engine No:	R18A1729242
Make & Model:	HONDA STREAM, 1.8 RSZ (A)	Chassis No:	RN61025923
Reg. Date:	08/06/2007 (Man. Year: 2007)	Odometer:	278230 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	LAUFENN 6 mm	Rear Left Side:	LAUFENN 6 mm
Front Right Side:	LAUFENN 6 mm	Rear Right Side:	LAUFENN 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,138.24	8,899.60	13,238.64	59.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,130.00	3,230.00	2,900.00	47.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>28,268.24</b>	<b>12,129.60</b>	<b>16,138.64</b>	<b>57.09</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>28,268.24</b>	<b>7,000.00</b>	<b>21,268.24</b>	<b>75.24</b>

#### INSPECTION

Date of Assignment:	04/01/2021		
Date Inspected:	05/01/2021	Inspected At:	15 Kaki Bukit Road 4 #01-05/53 Repairer: Zoom Autowerks Pte Ltd
Estimated Period of Repair:	10.0 days		

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2021)
<b>Parts:</b> M1-MPV	HONDA STREAM 1.8 RSZ (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJW2711D)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	966.90 FL	*665.40 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	112.00 FL	*- FL
3	2		*REAR BUMPER SIDE BRACKET	Not Necessary	996.40 FL	*- FL
4	1		*REAR BUMPER TOW GARNISH	Not Necessary	21.90 FL	*- FL
5	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*35.00 FL
6	1		*REAR END PANEL TOP GARNISH	Not Necessary	286.70 FL	*- FL
7	1		*REAR END PANEL	Badly Dented	806.50 FL	*316.00 FL
8	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
9	1		*REAR FLOOR PANEL	Repair	1,450.20 FL	*- FL
10	1		*REAR FLOOR PANEL TOP GARNISH	Not Necessary	320.50 FL	*- FL
11	1		*REAR SPARE TYRE BRACKET	Not Necessary	295.30 FL	*- FL
12	1		*REAR TAILGATE	Badly Dented	1,386.40 FL	*903.20 FL
13	1		*TAILGATE LOCK	Twisted/Shorted	459.40 FL	*145.80 FL
14	1		*TAILGATE LOCK CATCH	Not Necessary	96.10 FL	*- FL
15	2		*TAILGATE DAMPERS	Not Necessary	625.40 FL	*- FL
16	1		*TAILGATE WEATHER STRIP	Twisted	349.60 FL	*166.20 FL
17	1		*TAILGATE INNER TRIMBOARD	Deformed/Cracked	421.60 FL	*288.30 FL
18	1		*TAILGATE INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
19	1		*TAILGATE OUTER CENTRE GARNISH	Not Necessary	215.80 FL	*- FL
20	1		*TAILGATE LOGO	Not Necessary	98.50 FL	*- FL
21	1		*TAILGATE EMBLEM (STREAM)	Necessary	78.40 FL	*45.50 FL
22	1		*TAILGATE GLASS MOULDING	Necessary	115.20 FL	*68.20 FL
23	1		*TAILGATE GLASS	Shattered	1,286.70 FL	*1,280.20 FL
24	2		*REAR TAILLAMPS	Cracked	1,572.40 FL	*736.00 FL
25	1		*FRONT BUMPER	Dented/Deformed	925.30 FL	*654.20 FL
26	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	116.80 FL	*- FL
27	2		*FRONT BUMPER BRACKET	Not Necessary	144.60 FL	*- FL
28	1		*FRONT BUMPER REINFORCEMENT	Repair	352.80 FL	*- FL
29	1		*FRONT BUMPER CENTRE AIR-GRILLE	Not Necessary	215.20 FL	*- FL
30	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	291.80 FL	*- FL
31	2		*FRONT BUMPER FOG LAMP	Not Necessary	709.20 FL	*- FL
32	1		*BONNET	Buckled	938.90 FL	*685.20 FL
33	1		*BONNET INSULATOR	Not Necessary	195.80 FL	*- FL
34	1		*BONNET INSULATOR CLIPS	Not Necessary	60.00 FL	*- FL
35	1		*BONNET LOCK	Twisted	198.50 FL	*145.50 FL
36	1		*FRONT SUPPORT PANEL	Buckled	795.60 FL	*455.60 FL
37	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	175.60 FL	*- FL
38	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
39	1		*AC CONDENSER	Bent/Punctured	1,086.40 FL	*1,086.40 FL
40	1		*AC CONDENSER FAN COWLING ASSY	Not Necessary	552.50 FL	*- FL
41	1		*CONDENSER INLET HOSE	Not Necessary	295.60 FL	*- FL
42	1		*CONDENSER OUTLET HOSE	Not Necessary	286.70 FL	*- FL
43	1		*RADIATOR ASSY	Holder Cracked	2,159.70 FL	*1,687.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*RADIATOR TOP HOSE	Not Necessary	114.70 FL	*- FL
45	1		*RADIATOR BOTTOM HOSE	Not Necessary	98.70 FL	*- FL
46	1		*RADIATOR FAN COWLING ASSY	Not Necessary	583.80 FL	*- FL
47	2		*FRONT FENDER	Repair	1,573.80 FL	*- FL
48	2		*FRONT FENDER INNER SHIELD	Not Necessary	380.40 FL	*- FL
49	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
50	2		*FRONT HEADLAMP ASSY	Cracked	1,700.40 FL	*1,360.60 FL
51	2		*FRONT HEADLAMP BRACKET	Not Necessary	139.80 FL	*- FL
52	1		*FRONT ENGINE UNDER COVER	Not Necessary	295.80 FL	*- FL
53	1		*FRONT ENGINE UNDER COVER CLIPS	Not Necessary	60.00 FL	*- FL
54	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
55	1		*REAR TAILGATE GLASS INNER SEAL	Necessary	120.00 FS	*30.00 FS
56	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
57	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	65.00 FS	*- FS
58	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
59	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
60	1		*FRONT NUMBER PLATE W/GARNISH	Serviceable	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>27,480.30</b>	<b>11,044.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	5,342.06	2,144.90
<b>Total Parts (\$)</b>	<b>22,138.24</b>	<b>8,899.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY,SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,200.00	900.00
2	TO REMOVE & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	600.00
3	TO REMOVE & INSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	150.00	120.00
4	TO TRANSFER ALL TAILGATE COMPONENTS TO FACILITATE REPAIRS	New	200.00	60.00
5	TO TRANSFER ALL BOOTLID INTERIOR COMPONENTS TO FACILITATE REPAIRS	New	200.00	80.00
6	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	150.00	30.00
7	TO RE-POSITION & INSTALL REVERSE SENSOR	New	200.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
9	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	450.00	0.00
10	TO RUST PROOF AFFECTED REAR AREAS	New	200.00	90.00
11	TO REMOVE & RENEW FROTN AFFECTED ACCIDENT AREAS	New	1,000.00	600.00
12	TO PUTTY,SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,000.00	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,130.00</b>	<b>3,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >