

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI21000071/T1QD3Q2

**Date:** 01/02/2021

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: MU001607
<b>Claimant</b>	
<b>Vehicle No :</b> SHD3697D	<b>Insured Vehicle No :</b> SLK9366K
Date of Loss: 31/12/2020	Nature of Claim: TP Claim No: M2100016

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SHD3697D</b>	Engine No: D4FDEU461780
Make & Model: HYUNDAI I40, 1.7 D CRDi (A)	Chassis No: KMHLB41UMHU097195
Reg. Date: 15/12/2016 (Man. Year: 2016)	Odometer: 0 km
Colour: Blue	
Engine Capacity: 1685 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$): <b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition: Good

### CONDITION OF TYRES

Front Tyre Size: 205/60R16	Rear Tyre Size: 205/60R16
Front Left Side: West Lake 6 mm	Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm	Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,414.34	1,520.50	2,893.84	65.56
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,620.00	510.00	1,110.00	68.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,045.34</b>	<b>2,041.50</b>	<b>4,003.84</b>	<b>66.23</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,650.00</b>		
<b>(\$\$)</b>	6,045.34	1,650.00	4,395.34	72.71
<b>+ GST 7.00/7.00% (\$\$)</b>	423.17	115.50	307.67	72.71
<b>Nett Amount (\$\$)</b>	<b>6,468.51</b>	<b>1,765.50</b>	<b>4,703.01</b>	<b>72.71</b>

### INSPECTION

Date of Assignment:	04/01/2021 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	04/01/2021 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2021)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD3697D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Deformed	1,106.00 FL	-	*1,106.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER SPONGE	Not Necessary	119.50 FL	-	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	-	*- FL
5	1		*REAR BUMPER LOWER COVER	Deformed	228.00 FL	-	*228.00 FL
6	1		*REAR BUMPER REVERSE SENSOR	Not Working	135.70 F	-	*135.70 F
7	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 F
8	1		*REAR PANEL ASSY	Not Necessary	526.70 FL	-	*- FL
9	1		*REAR PANEL TRIM-TRANSVERSE TOP	Not Necessary	57.60 FL	-	*- FL
10	1		*BOOTLID ASSY	Not Necessary	2,174.90 FL	-	*- FL
11	1		*BOOTLID LATCH ASSY	Not Necessary	114.90 FL	-	*- FL
12	1		*BOOTLID EMLEM - I40	Not Necessary	67.90 FL	-	*- FL
13	1		*BOOTLID EMLEM - CRDI	Not Necessary	52.40 FL	-	*- FL
14	1		*BOOTLID COMFORTDELGRO LOGO CTPL	Not Necessary	30.00 F	-	*- F
15	1		*BOOTLID TEL NO STICKER CTPL	Not Necessary	30.00 F	-	*- F
16	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	-	*50.00 F
17	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 F	-	*100.00 F
18	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,394.00</b>	<b>1,791.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	979.66	271.20
<b>Total Parts (\$\$)</b>	<b>4,414.34</b>	<b>1,520.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	850.00	280.00
2	SPRAY PAINTING CHARGE	New	650.00	200.00
3	REVE/REFIX REVERSE SENSOR	New	120.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,620.00</b>	<b>510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >