

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000077/T1TD3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00038402001

**Claimant
Vehicle No :** SME2541L

**Insured
Vehicle No :** GBD8646P

Date of Loss: 01/01/2021

Nature of
Claim: TP

Claim
No: SNM21D200016/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME2541L**

Make & Model: BMW X1, 1.5 SDRIVE 18i (A)

Engine No: F773H847B38B15A

Reg. Date: 24/09/2018 (Man. Year: 2018)

Chassis No: WBAJG120403G76288

Colour: Black

Odometer: 21276 km

Engine Capacity: 1499 cc

Market Value/New Car

N/A

Price:

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R18 Rear Tyre Size: 225/50R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,616.49	4,018.19	1,598.30	28.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,272.00	6,532.00	2,740.00	29.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,888.49	10,550.19	4,338.30	29.14
+ GST 7.00/7.00% (\$\$)	1,042.19	738.51	303.68	29.14
Nett Amount (\$\$)	15,930.68	11,288.70	4,641.98	29.14

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 05/01/2021 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2021)
Parts:	M1-SUV	BMW X1 1.5 SDRIVE 18I (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME2541L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*SCREW SELF TAPPING	Not Necessary	2.40 FS	*- FS
2	1		*RR BUMPER CARRIER	Not Necessary	496.35 FS	*- FS
3	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	143.35 FS	*- FS
4	1		*RR BUMPER RH CORNER MOUNTING	Not Necessary	143.35 FS	*- FS
5	1		*REAR BUMPER LH MOUNT (M)	Not Necessary	162.25 FS	*- FS
6	1		*REAR BUMPER RH MOUNT (M)	Not Necessary	162.25 FS	*- FS
7	1		*MOUNTING SMART OPENER (M)	Not Necessary	45.75 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED (M/PDC)	Deformed	1,191.60 FS	*1,191.60 FS
9	1		*REAR BUMPER TRIM PANEL BOTTOM (M/PD)	Deformed	297.80 FS	*297.80 FS
10	1		*LETTERING S DRIVE 18I	Necessary	97.15 FS	*97.15 FS
11	1		*LETTERING X1	Necessary	64.75 FS	*64.75 FS
12	10		*BUMP STOP	Necessary	32.00 FS	*32.00 FS
13	1		*REAR WINDOW (ESG)	Cracked	851.00 FS	*851.00 FS
14	10		*HOOK AND LOOP FASTENER	Not Necessary	28.50 FS	*- FS
15	1		*AEROBLADE (SCHWARZ)	Not Necessary	393.50 FS	*- FS
16	1		*REAR RH LIGHT IN TRUNK LID	Cut	279.90 FS	*279.90 FS
17	1		*REAR RH LIGHT IN THE SIDE PANEL	Cracked	399.85 FS	*399.85 FS
18	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.60 FS	*- FS
19	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
20	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
21	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
22	1		*PREMIUM REAR WINDSCREEN SOLAR FILM	Torn	252.34 FS	*252.34 FS
23	1		*RH PANEL TAIL LID (SCHWARZ)	Cut	31.65 FS	*31.65 FS
24	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
25	1		*REAR REFLECTOR REAR RH	Cracked	39.05 FS	*39.05 FS
26	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 5,616.49 4,018.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER PANEL AND ATTACHMENTS,REAR SPOILER,REWORK BOOTLID,REAR RIGHT SIDE PANEL	New	4,250.00	2,550.00
2	TO RESPRAY REAR BUMPER,BOOTLID,REAR SPOILER,REAR RIGHT SIDE PANEL	New	3,339.00	3,005.00
3	TO REPLACE REAR WINDSCREEN GLASS	New	676.00	574.00
4	TO CONDUCT WATER LEAK TESTS	New	75.00	63.00
5	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
6	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
7	VACUUM GLASS DEBRIS	New	224.00	190.00
Gross Labour Cost (\$\$)			9,272.00	6,532.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >