

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000080/AEA3Q2
Date: 10/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900233376
Claimant Vehicle No :	SLC4177P	Insured Vehicle No :	SMP9223B
Date of Loss:	17/12/2020	Nature of Claim:	TP
		Claim No:	6059617335SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC4177P	Engine No:	1NZZ326628
Make & Model:	TOYOTA VIOS, 1.5 E GRADE (A)	Chassis No:	MHFBT9F3906065324
Reg. Date:	13/05/2016 (Man. Year: 2015)	Odometer:	61056 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,593.20	659.90	2,933.30	81.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	480.00	740.00	60.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,813.20	1,139.90	3,673.30	76.32
Approved Total (Overridden) (S\$)		900.00		

(S\$)	4,813.20	900.00	3,913.20	81.30
+ GST 7.00/7.00% (S\$)	336.92	63.00	273.92	81.30
Nett Amount (S\$)	5,150.12	963.00	4,187.12	81.30
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,090.45		
Global Sum Settlement (S\$)		1,090.00		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 28/12/2020

Inspected At:

New Zen Werkz Pte Ltd (HQ)
 Blk 3 kaki Bukit road 1 #03-04 Eunost Technolink
 Singapore 415935

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	895.00 F	*- FL
2	2		*REAR TAIL LAMP	Not Necessary	624.40 F	*- FL
3	4		*REAR TAIL LAMP CLIPS	Not Necessary	51.60 F	*- FL
4	1		*REAR BUMPER	Deformed	455.20 F	*455.20 FL
5	2		*REAR BUMPER SIDE BRACKET	Necessary	263.40 F	*128.00 FL
6	2		*REAR BUMPER RETAINER	Not Necessary	370.40 F	*- FL
7	2		*REAR BUMPER BEAM	Not Necessary	128.00 F	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	352.00 F	*- FL
9	1		*REAR BUMPER REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
10	8		*REAR BUMPER CLIPS	Necessary	103.20 F	*30.00 FL
11	1		*REAR NUMBER PLATE	Not Necessary	50.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,593.20	813.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	153.30
Total Parts (\$\$)	3,593.20	659.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX CUSHION	New	120.00	0.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
3	TUFF KOTE	New	120.00	0.00
4	TO CHECK WIRING SYSTEM	New	60.00	30.00
5	PANEL BEATING	New	400.00	200.00
6	SPRAY PAINTING	New	400.00	200.00
Gross Labour Cost (S\$)			1,220.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >