

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000084/KVD3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001207179

Claimant Vehicle No : SLG9539A

Insured Vehicle No : YP9942S

Date of Loss: 01/01/2021

Nature of Claim: TP

Claim No: 251597

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG9539A**

Make & Model: TOYOTA AQUA HYBRID, 1.5 E S CVT (A)

Engine No: 1NZ8021428

Reg. Date: 19/10/2016 (Man. Year: 2016)

Chassis No: NHP106532322

Colour: White

Odometer: 312523 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R16

Rear Tyre Size: 195/55R16

Front Left Side: KAPSEN 3 mm

Rear Left Side: SUNWIDE 4 mm

Front Right Side: KAPSEN 3 mm

Rear Right Side: SUNWIDE 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,618.82	1,984.80	3,634.02	64.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	940.00	2,160.00	69.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,718.82	2,924.80	5,794.02	66.45
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	8,718.82	2,300.00	6,418.82	73.62
+ GST 7.00/7.00% (S\$)	610.32	161.00	449.32	73.62
Nett Amount (S\$)	9,329.14	2,461.00	6,868.14	73.62

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 05/01/2021 Inspected At:

Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A,
#01-05 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2021)
Parts:	144	TOYOTA AQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG9539A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	477.70 FL	*477.70 FL
2	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	48.30 FL	*48.30 FL
3	1		*FRONT FENDER INNER SHIELD RH	Distorted	216.90 FL	*216.90 FL
4	1		*FRONT SIDE MIRROR ASSY	Dented/Cracked	857.60 FL	*857.60 FL
5	1		*FRONT DOOR RH	Bent	1,241.00 FL	*1,005.90 FL
6	1		*FRONT TYRE RH	Serviceable	240.00 FL	*- FL
7	1		*FRONT WHEEL RIM RH	Serviceable	263.70 FL	*- FL
8	1		*FRONT WHEEL CAP RH	Serviceable	180.60 FL	*- FL
9	1		*FRONT ABSORBER RH	Serviceable	463.20 FL	*- FL
10	1		*FRONT LOWER ARM RH	Serviceable	457.80 FL	*- FL
11	1		*FRONT KNUCKLE ARM RH	Serviceable	594.60 FL	*- FL
12	1		*FRONT WHEEL BEARING RH	Not Necessary	168.90 FL	*- FL
13	1		*FRONT TIE ROD END RH	Serviceable	186.70 FL	*- FL
14	1		*REAR DOOR RH	Repair	1,045.00 FL	*- FL
15	1		*REAR BUMPER (DENTED)	Not Consistent With The Impact	878.70 FL	*- FL
16	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	64.40 FL	*- FL
17	1		*FRONT SIDE A-PILLAR RH (NPA)	Repair	0.00 FL	*- FL
18	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
19	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	30.00 FS	*30.00 FS
20	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,465.10	2,636.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,846.28	651.60
Total Parts (\$\$)	5,618.82	1,984.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC	New	1,200.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT FENDER RH,FRONT DOOR RH,FRONT SIDE A-PILLAR RH,REAR DOOR RH,REAR FENDER RH,REAR BUMPER & ETC	New	1,300.00	460.00
3	LABOUR CHARGES TO REMOVE,REPLACE,REFIX FRONT DASHBOARD RH,FRONT LOWER ARM RH,FRONT KNUCKLE ARH & ETC	New	200.00	0.00
4	TO WHEEL ALIGNMENT & BALANCING	New	80.00	0.00
5	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR RH INNER MECHANISM & ETC.TO EFFECT REPLACE OF FRONT & REAR DOOR RH	New	240.00	60.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$\$)			3,100.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >