

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21000088/T1VD3Q2
Date: 20/01/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	ML000128
Claimant		
Vehicle No : SHC6229H	Insured Vehicle No :	SLL783T
Date of Loss: 31/12/2020	Nature of Claim:	TP
		Claim No: M2100022

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6229H		
Make & Model:	KIA OPTIMA, 1.7 D (A)	Engine No:	D4FDEH311473
Reg. Date:	23/10/2014 (Man. Year: 2014)	Chassis No:	KNAGM414MF5542431
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,132.90	60.00	1,072.90	94.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	760.00	1,210.00	61.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,102.90	820.00	2,282.90	73.57
+ GST 7.00/7.00% (S\$)	217.20	57.40	159.80	73.57
Nett Amount (S\$)	3,320.10	877.40	2,442.70	73.57

INSPECTION

Date of Assignment:	04/01/2021	
Date Inspected:	04/01/2021	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2021)
Parts: 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC6229H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Repair	696.00 FL	-	*- FL
2	1		*REAR BUMPER SIDE BRACKET O/S	Not Necessary	29.00 FL	-	*- FL
3	1		*REAR O/S WHEEL COVER	Not Necessary	116.00 FL	-	*- FL
4	1		*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	-	*- FS
5	1		*REAR BUMPER TOP PROTECTOR	Not Necessary	80.00 FS	-	*- FS
6	1		*REAR O/S FENDER STICKER	Necessary	60.00 FS	-	*60.00 FS
7	1		*SET O/S DOOR STICKERS	Not Necessary	100.00 FS	-	*- FS
8	1		*SET O/S ROCKER PANEL GARNISH CLIPS	Not Necessary	38.00 FS	-	*- FS
9	1		*SUNDRY	Not Necessary	50.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,217.00	60.00
- List Item Discount on L Items 10.00/10.00% (S\$)	84.10	0.00
Total Parts (S\$)	1,132.90	60.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR O/S WHEEL ALIGNMENT	New	80.00	0.00
2	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE REAR O/S FENDER,REAR O/S DOOR,REAR O/S ROCKER PANEL GARNISH,ETC	New	850.00	300.00
4	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,REAR O/S FENDER,REAR O/S DOOR,REAR O/S ROCKER PANEL GARNISH	New	800.00	400.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	30.00
			Gross Labour Cost (\$\$)	1,970.00
				760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >