

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000091/QTD3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001350940

Claimant
Vehicle No : GBB5942P

Insured Vehicle No : GBE6533P

Date of Loss: 29/12/2020

Nature of Claim: TP

Claim No: 251512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB5942P**

Make & Model: TOYOTA DYNA 100 MANUAL, 3.0 D (M)

Engine No: 1KD1939409

Reg. Date: 04/08/2009 (Man. Year: 2009)

Chassis No: JTFAT35Y10K200814

Colour: White

Odometer: 388829 km

Engine Capacity: 2982 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 195R15

Front Left Side: GREEN-MAX 6 mm

Rear Left Side: GREEN-MAX 6 mm

Front Right Side: GREEN-MAX 6 mm

Rear Right Side: GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,013.25	1,575.15	1,438.10	47.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	900.00	1,110.00	55.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,023.25	2,475.15	2,548.10	50.73
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	5,023.25	2,000.00	3,023.25	60.19
+ GST 7.00/7.00% (S\$)	351.63	140.00	211.63	60.19
Nett Amount (S\$)	5,374.88	2,140.00	3,234.88	60.19

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 04/01/2021 Inspected At:

Carz Auto Services Pte Ltd -
Woodlands (HQ)
NO 61, WOODLANDS INDUSTRIAL
PARK E9, #04-04 E9 PREMIUM
SINGAPORE 757047
Singapore 757047

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Feb 2021)	
Parts:	N/A	TOYOTA DYNA 100 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB5942P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,585.80 FL	*1,315.00 FL
2	1		*TAIL GATE TOYOTA STICKER	Necessary	145.20 FL	*145.20 FL
3	1		*TAIL GATE DYNA STICKER	Necessary	65.50 FL	*50.00 FL
4	1		*TAIL GATE LOWER PANEL	Repair	644.20 FL	*- FL
5	1		*TAIL GATE LOWER PANEL STICKER	Necessary	71.30 FL	*50.00 FL
6	1		*REAR NUMBER PLATE HOLDER	Bent	210.90 FL	*160.00 FL
7	1		*REAR NUMBER PLATE LAMP	Serviceable	48.90 FL	*- FL
8	2		*REAR TAIL LAMP	Serviceable	477.40 FL	*- FL
9	2		*REAR TAIL LAMP PANEL	Repair	221.80 FL	*- FL
10	1		*TAIL GATE 70KM/H STICKER	Necessary	25.00 FS	*25.00 FS
11	1		*TAIL GATE 13 PAX STICKER	Necessary	25.00 FS	*25.00 FS
12	1		*REAR NUMBER PLATE	Scratched	50.00 FS	*35.00 FS
13	1		*REAR TAIL LAMP REFLECTOR LH	Not Necessary	30.00 FS	*- FS
14	1		*REAR REVERSE SENSOR	Missing	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,881.00	2,005.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	867.75	430.05
Total Parts (\$\$)	3,013.25	1,575.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & RENEW REAR DAMAGED PARTS;REPLACE REALIGNED ALL AFFECTED PARTS	New	800.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	400.00
3	TO REMOVE/REFIX WIRING CHECKS	New	60.00	30.00
4	TO TUFFCOAT AFFECTED AREA	New	150.00	40.00
5	TO REMOVE/REPLACE REVERSE SENSORS	New	100.00	30.00
6	TO REMOVE AND REPLACE TAIL GATE MECHANISM	New	100.00	0.00
Gross Labour Cost (\$\$)			2,010.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >