

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III21000113/R1BA3Q2

Date: 08/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0006766
Claimant Vehicle No :	SMF9168E	Insured Vehicle No :	SJR8880K
Date of Loss:	02/01/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0000058

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF9168E		
Make & Model:	BMW 318I, 1.5 LED (A)	Engine No:	31705483B38B15A
Reg. Date:	29/11/2018 (Man. Year: 2018)	Chassis No:	WBA8E32060A554220
Colour:	Black	Odometer:	32940 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,173.40	1,984.80	1,188.60	37.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,663.40	3,918.80	1,744.60	30.80
+ GST 7.00/7.00% (\$\$)	396.44	274.32	122.12	30.80
Nett Amount (\$\$)	6,059.84	4,193.12	1,866.72	30.80
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,375.12		

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 18/01/2021 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2021)
Parts:	143	BMW 318i 1.5 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF9168E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*RR BUMPER BOTTOM REINFORCEMENT	Cracked	73.05 FS	*73.05 FS
3	1		*REAR BUMPER CENTRE GUIDE	Cracked	56.05 FS	*56.05 FS
4	1		*REAR BUMPER CARRIER (ECE)	Bent	470.25 FS	*470.25 FS
5	1		*REAR BUMPER TOWING EYE COVER PRIMED	Serviceable	43.70 FS	*- FS
6	1		*REAR BUMPER PANEL PRIMED (BASIS)	Deformed	1,184.75 FS	*1,184.75 FS
7	1		*(S/L) LH PROTECTION FOIL	Not Necessary	10.75 FS	*- FS
8	1		*(S/L) RH PROTECTION FOIL	Not Necessary	10.75 FS	*- FS
9	1		*SET MOUNTING PDC/PMA SENSOR REAR	Necessary	67.65 FS	*67.65 FS
10	1		*REAR LH REFLECTOR	Not Necessary	37.90 FS	*- FS
11	1		*REAR RH REFLECTOR	Not Necessary	37.90 FS	*- FS
12	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.60 FS	*- FS
13	4		*ULTRASONIC SENSOR BLACK	Not Necessary	957.00 FS	*- FS
14	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,173.40** **1,984.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC AND CARRYOUT NECESSARY REPAIRS	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >