

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21000122/GVD3E2  
**Date:** 08/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100493136  
**Claimant Vehicle No** : SMN6938C **Insured Vehicle No :** SBR5112J  
Date of Loss: 30/12/2020 Nature of Claim: TP Claim No: 0083363004SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN6938C**  
Make & Model: BMW 535i GT, 3.0 D/AB 2WD GAS/D TC HUD SR (A) Engine No: 02367768N55B30A  
Reg. Date: 31/05/2011 (Man. Year: 2011) Chassis No: WBAFR72060C581215  
Colour: White Odometer: 0 km  
Engine Capacity: 2979 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/30ZR20 Rear Tyre Size: 225/30ZR20  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 04/01/2021  
Date Inspected: 05/01/2021 Inspected At: 1st Auto Pro Pte Ltd - 8 Kaki Bukit (HQ)  
8 Kaki Bukit Avenue 4, #01-51/52 PREMIER @ KAKI BUKIT  
Singapore 415875  
Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Cut	0.00 F	*- F
4	1		*FRT BUMPER NOZZLE	Broken	0.00 F	*- F
5	1		*FRT BUMPER NOZZLE COVER	Missing	0.00 F	*- F
6	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
7	1		*FRT RH FENDER	Repair	0.00 F	*- F
					<b>Total Parts (\$\$)</b>	<b>0.00</b>
						<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >