

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21000126/AQD3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070050694

Claimant
Vehicle No : GZ3546C **Insured Vehicle No :** GBJ5393G

Date of Loss: 02/01/2021 Nature of Claim: TP Claim No: 7314832156SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ3546C	Engine No:	QD32218897
Make & Model:	NISSAN CABSTAR, 3.0 (M)	Chassis No:	JN1SF4F23Z0860841
Reg. Date:	16/03/2006 (Man. Year: 2005)	Odometer:	172984 km
Colour:	White		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	155 R12C
Front Left Side:	OHTSU 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,812.57	5,376.85	12,435.72	69.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,585.00	3,740.00	1,845.00	33.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,397.57	9,116.85	14,280.72	61.04
Approved Total (Overridden) (\$\$)		7,300.00		
Nett Amount (\$\$)	23,397.57	7,300.00	16,097.57	68.80

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 05/01/2021 Inspected At:

Cheng Motor Work Co. (HQ)
1 KAKI BUKIT AVE 6 #01-83
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	1,212.10 FN	*1,212.10 FN
2	1		*FRONT WINDSCREEN RUBBER	Necessary	158.70 FN	*158.70 FN
3	1		*REAR CROSS MEMBER	Repair	1,579.20 FN	*- FN
4	2		*ENGINE MOUNTING	Not Necessary	312.00 FN	*- FN
5	1		*REAR EXHAUST SILENCER BOX PIPE	Repair	545.00 FN	*- FN
6	2		*REAR EXHAUST MOUNTING	Not Necessary	90.00 FN	*- FN
7	2		*TAIL LAMP	Cracked	497.20 FN	*497.20 FN
8	2		*TAIL LAMP PANEL	Bent	326.80 FN	*326.80 FN
9	1		*END PANEL	Dented	680.00 FN	*495.00 FN
10	1		*TAIL GATE	Dented	1,399.70 FN	*1,399.70 FN
11	2		*TAILGATE HANDLE	Not Necessary	130.00 FN	*- FN
12	2		*TAIL SIDE GATE	Repair	3,958.20 FN	*- FN
13	1		*REAR DECK BODY FLOOR PANEL	Repair	1,022.00 FN	*- FN
14	1		*TOW HOOK	Not Necessary	98.00 FN	*- FN
15	1		*TAIL GATE SIDE LOCK	N/s Bent	464.40 FN	*232.20 FN
16	3		*TAIL GATE HINGES	Bent	171.60 FN	*171.60 FN
17	1		*SPARE TYRE HOLDER LOCK	Damaged	198.70 FN	*198.70 FN
18	1		*SPARE TYRE HOLDER PLATE	Not Necessary	67.90 FN	*- FN
19	4		*STOPPER	Missing	120.00 FN	*120.00 FN
20	1		*NUMBER PLATE LAMP	Not Necessary	48.80 FN	*- FN
21	1		*NUMBER PLATE PANEL	Bent	79.20 FN	*79.20 FN
22	1		*REAR DECK BODY ASSY	Repair	5,082.50 FN	*- FN
23	1		*EXHAUST TUBE	Dented	305.30 FN	*305.30 FN
24	1		*TAILGATE CHECKER PLATE	Bent	600.00 FS	*300.00 FS
25	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
26	1		*REVERSER SENSOR	Damaged	280.00 FS	*200.00 FS
27	1		*REVERSER SENSOR BRACKET	Damaged	80.00 FS	*60.00 FS
28	1		*70KM STICKER	Necessary	20.00 FS	*10.00 FS
29	1		*8 PAX STICKER	Necessary	20.00 FS	*10.00 FS
30	1		*IU BRACKET	Necessary	30.00 FS	*30.00 FS
31	1		*WINDSCREEN GUM	Necessary	60.00 FS	*60.00 FS
					Sub Total (\$\$)	19,667.30 5,896.50
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,854.73 519.65
					Total Parts (\$\$)	17,812.57 5,376.85

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO JACK OUT,STRAIGHTEN CHASSIS FRAME,RENEW REAR CROSS MEMBER	New	1,000.00	400.00
2	TO LIFT UP REAR BODY FOR STRAIGHTEN CHASSIS	New	600.00	400.00
3	TO KNOCKING,CUTTING,WELDING,RENEW FLOOR PANEL,SIDE GATE,TAIL GATE AND ALL THE DAMAGE PARTS	New	1,500.00	1,300.00
4	TO SPRAY PAINT ON THE DAMAGE PARTS	New	1,500.00	1,200.00
5	TUFF KOTE	New	200.00	60.00
6	TO REMOVE/RENEW REAR REVERSER SENSOR	New	150.00	60.00
7	TO REMOVE/RENEW TAILGATE CHECKER PLATE	New	200.00	50.00
8	TO REMOVE/RENEW REAR EXHAUST PIPE	New	120.00	0.00
9	TO REMOVE/RENEW FRONT WINDSCREEN GLASS	New	150.00	120.00
10	TO CHECK WIRING	New	45.00	30.00
11	LABOR FOR REPLACED	New	120.00	120.00
Gross Labour Cost (\$\$)			5,585.00	3,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >