



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 5517A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER LH	DENTED	622.10	585.00
1	FRONT FENDER INNER SHIELD LH	TORN	171.20	171.20
1	FRONT FENDER "VVTI" EMBLEM LH	NECESSARY	42.10	42.10
1	FRONT BUMPER	DEFORMED	563.60	563.60
2	FRONT BUMPER SIDE RETAINER L/R @\$55.20	N/S NECESSARY	110.40	55.20
1	FRONT BUMPER SEAL	NOT NECESSARY	52.50	-
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	298.10	-
1	FRONT BUMPER FOG LAMP GARNISH LH	NOT NECESSARY	62.00	-
1	FRONT BUMPER REINFORCEMENT BEAM	NOT NECESSARY	393.90	-
1	FRONT BUMPER LOWER GRILLE	CRACKED	152.80	152.80
1	FRONT GRILLE	NOT NECESSARY	314.90	-
1	FRONT GRILLE "LOGO" EMBLEM	NOT NECESSARY	71.60	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	721.30	-
1	FRONT BRACE PANEL	NOT NECESSARY	115.70	-
1	FRONT HEADLAMP LH	CRACKED	713.80	713.80
1	AIR RESONATOR ASSY	NOT NECESSARY	240.10	-
	LESS 25% DISCOUNT		-1,161.53	-570.93
			3,484.57	1,712.77
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NO PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT NO PLATE GARNISH (SN)	NOT NECESSARY	50.00	-
1	FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	30.00	30.00
			135.00	60.00
	<u>LABOUR</u>			
	TO CHECK FRONT ELECTRICAL WIRING SYSTEM.		80.00	30.00
	TO STRAIGHTEN,REPAIR,REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		800.00	400.00

Report Ref No. CS/AGI21000133/Aqd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON AFFECTED AREA.		800.00	400.00
			1,680.00	830.00
GRAND TOTAL			5,299.57	2,602.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/AGI21000133/Aqd3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.