LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG21000136/GVD3E2

Date:

14/01/2021

Claim No:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100431329

Claimant Vehicle No

SJV1010E

Insured Vehicle No:

SKV6958B

Date of Loss:

02/01/2021

Nature of Claim:

ΤP

5907904900SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJV1010E

Make & Model: Reg. Date:

Engine Capacity:

TOYOTA HARRIER, 2.0 Premium (A) 29/03/2018 (Man. Year: 2017)

Engine No: Chassis No: Odometer:

8ARZ088047 ASU600003253

69236 km

Colour:

White 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size:

235/55 R18

Rear Tyre Size:

235/55 R18

Front Left Side: Front Right Side: Dunlop 6 mm Dunlop 6 mm Rear Left Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	-
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

05/01/2021

889 Car Servicing Pte Ltd

Date Inspected:

Adjuster:

07/01/2021

Inspected At:

10 Kaki Bukit Road 2, #03-34 First East Centre

Singapore 417868

Estimated Period of Repair:

XING GUO QIANG

3.0 days

Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*-F
4	1		*FRT BUMPER BEAM	Repair	0.00 F	*-F
5	1		*FRT BUMPER SPONGE	Broken	0.00 F	*-F
6	1		*FRT GRILLE	Cracked	0.00 F	*-F
7	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
8	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*-F
F=Fra	anchise	part.				
				Total Parts (S\$)	0.00	0.00
			Report was unsubmit	ted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >