

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000137/QVD3E2

Date: 27/01/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900168381		
Claimant Vehicle No :	JQV4570	Insured Vehicle No :	SCN2878L		
Date of Loss:	02/12/2020	Nature of Claim:	TP	Claim No:	5427678653SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JQV4570	Engine No:	HIDDEN
Make & Model:	KAWASAKI ER250, 249cc	Chassis No:	HIDDEN
Reg. Date:	(Man. Year:)	Odometer:	68827 km
Colour:	Orange		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-17	Rear Tyre Size:	120/70-17
Front Left Side:	Cheng Shin 5 mm	Rear Left Side:	Cheng Shin 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	05/01/2021	
Date Inspected:	05/01/2021	Inspected At: At Assure Motoring (HQ) Blk 5032 Ang Mo Kio Industrial Park 2, #01-307 Singapore 569535
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT WING MIRROR	Crumpled	0.00 F	*- F
3	1		*HANDLE BAR	Bent	0.00 F	*- F
4	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
5	1		*HANDLE BAR BALANCER RH	Necessary	0.00 F	*- F
6	1		*FUEL TANK	Repair	0.00 F	*- F
7	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
8	2		*SIDE FAIRING	Scratched	0.00 F	*- F
9	1		*SIDE FAIRING TOP GARNISH LH	Crushed	0.00 F	*- F
10	1		*REAR FAIRING LH	Scratched	0.00 F	*- F
11	1		*FOOT BRAKE	Bent	0.00 F	*- F
12	1		*FRONT FOOT REST LH	Bent	0.00 F	*- F
13	1		*FRONT FOOT REST BRACKET LH	Crumpled	0.00 F	*- F
14	1		*EXHAUST MUFFLER ASSY	Scratched	0.00 F	*- F
15	1		*LH SIDE BALANCER	Bent	0.00 F	*- F
16	1		*FRONT FOOT GEAR LEVER	Bent	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >