

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21000141/ETD3E2  
**Date:** 05/02/2021

### REFERENCE

Insured/Claimant: ZHUO YONGZHONG Policy No: 1900177369  
Date of Loss: 05/01/2021 Nature of Claim: OD Claim No: 4549263448SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP6894J**  
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11BD7753  
Reg. Date: 10/10/2019 (Man. Year: 2019) Chassis No: GF7W0601719  
Colour: White Odometer: 16058 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$100,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm  
Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,570.63	6,057.57	8,513.06	58.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,290.00	4,750.00	3,540.00	42.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,860.63</b>	<b>10,807.57</b>	<b>12,053.06</b>	<b>52.72</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>22,560.63</b>	<b>10,507.57</b>	<b>12,053.06</b>	<b>53.43</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,579.24</b>	<b>735.53</b>	<b>843.71</b>	<b>53.43</b>
<b>Nett Amount (S\$)</b>	<b>24,139.87</b>	<b>11,243.10</b>	<b>12,896.77</b>	<b>53.43</b>

### INSPECTION

Date of Assignment: 05/01/2021  
Date Inspected: 05/01/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 12.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
2	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Broken	1,048.00 FL	*1,048.00 FL
4	1		*EXTENSION, FR BUMPER	Not Necessary	515.00 FL	*- FL
5	1		*GARNISH, FR BUMPER, LH	Cut	48.00 FL	*48.00 FL
6	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 FL	*18.00 FL
7	1		*GARNISH, FR BUMPER SIDE	Missing	48.00 FL	*48.00 FL
8	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
9	1		*GARNISH, FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
10	1		*COVER, FR BUMPER	Not Necessary	359.00 FL	*- FL
11	1		*REINF, FR BUMPER SIDE, LH	Not Necessary	60.00 FL	*- FL
12	1		*BAR, FR BUMPER GUARD	Not Necessary	130.00 FL	*- FL
13	1		*REINFORCEMENT, FR BUMPER	Not Necessary	490.00 FL	*- FL
14	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	50.00 FL	*- FL
15	1		*GRILLE ASSY, RADIATOR	Not Necessary	548.00 FL	*- FL
16	1		*COVER, FR BUMPER	Not Necessary	25.00 FL	*- FL
17	1		*BRACKET, RADIATOR GRILLE, LH	Not Necessary	13.00 FL	*- FL
18	1		*BRACKET, RADIATOR GRILLE, RH	Not Necessary	17.00 FL	*- FL
19	1		*HOOD	Dented	975.00 FL	*975.00 FL
20	1		*HINGE, HOOD, LH	Not Necessary	68.00 FL	*- FL
21	1		*HINGE, HOOD, RH	Not Necessary	68.00 FL	*- FL
22	8		*CLIP, HOOD INSULATOR	Not Necessary	24.00 FL	*- FL
23	1		*WEATHERSTRIP, HOOD	Not Necessary	41.00 FL	*- FL
24	1		*WEATHERSTRIP, HOOD	Not Necessary	40.00 FL	*- FL
25	2		*DAMPER, HOOD	Not Necessary	6.00 FL	*- FL
26	4		*TAPE, BONNET	Necessary	16.00 FL	*16.00 FL
27	1		*LATCH, HOOD	Not Necessary	76.00 FL	*- FL
28	1		*ENGINE HOOD EMBLEM	Necessary	80.00 FL	*80.00 FL
29	1		*FENDER, FR LH	Dented	688.00 FL	*688.00 FL
30	1		*INSULATOR, FR FENDER, LH	Crushed	60.00 FL	*60.00 FL
31	1		*SHIELD, FR WHEELHOUSE, LH	Torn	164.00 FL	*164.00 FL
32	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	348.00 FL	*- FL
33	1		*PANEL, HEADLAMP SUPPORT, LWR	Not Necessary	107.00 FL	*- FL
34	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	182.00 FL	*- FL
35	1		*PNL, HEADLAMP SUPT, UPR LH	Dented	58.00 FL	*58.00 FL
36	1		*MOULDING, FR BUMPER, LH	Missing	116.00 FL	*116.00 FL
37	1		*MOULDING, FR WHEEL ARCH, LH	Cut	160.00 FL	*160.00 FL
38	1		*GARNISH, FR DECK	Not Necessary	173.00 FL	*- FL
39	1		*COVER, FR DECK, LH	Missing	19.00 FL	*19.00 FL
40	1		*COVER, FR DECK GARNISH, LH	Not Necessary	22.00 FL	*- FL
41	1		*GARNISH, FR DOOR, LH	Not Necessary	190.00 FL	*- FL
42	1		*TAPE, FR DOOR SASH, LH	Necessary	42.00 FL	*42.00 FL
43	1		*TAPE, RR DOOR SASH	Necessary	42.00 FL	*42.00 FL
44	1		*PANEL ASSY, FR DOOR, LH	Dented	977.00 FL	*977.00 FL
45	1		*HINGE, FR DOOR, UPR LH	Not Necessary	43.00 FL	*- FL
46	1		*HINGE, FR DOOR LWR LH	Not Necessary	43.00 FL	*- FL
47	1		*HEADLAMP ASSY, LH	Broken	1,938.00 FL	*1,938.00 FL
48	1		*LAMP ASSY, FOG, FR LH	Not Necessary	348.00 FL	*- FL
49	1		*WHEEL, DISC LHF	Cut	974.00 FL	*974.00 FL
50	1		*SHAFT AS, FR AXLE DRIVE, LH	Not Necessary	1,285.00 FL	*- FL
51	1		*CROSSMEMBER, FR AXLE, NO.1	Not Necessary	1,114.00 FL	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*ARM ASSY, FR SUSP, LWR LH	Not Necessary	323.00 FL	*- FL
53	1		*BAR, FR SUSP STABILIZER	Not Necessary	291.00 FL	*- FL
54	1		*STRUT, FR SUSP, LH	Not Necessary	406.00 FL	*- FL
55	1		*BEARING, FR SUSP STRUT	Not Necessary	32.00 FL	*- FL
56	1		*LINK, FR SUSP STABILIZER	Not Necessary	137.00 FL	*- FL
57	1		*KNUCKLE, LH	Not Necessary	356.00 FL	*- FL
58	1		*BEARING, FR WHEEL HUB	Not Necessary	151.00 FL	*- FL
59	1		*HUB ASSY, FR WHEEL	Not Necessary	286.00 FL	*- FL
60	1		*HOSE, FR BRAKE, LH	Not Necessary	50.00 FL	*- FL
61	1		*SENSOR, FR ABS, LH	Not Necessary	240.00 FL	*- FL
62	1		*GEAR & LINK ASSY, STEERING	Not Necessary	1,399.00 FL	*- FL
63	1		*END ASSY, TIE ROD	Not Necessary	65.00 FL	*- FL
64	1		*MIRROR ASSY, DOOR, LH	Not Necessary	555.00 FL	*- FL
65	1		*COVER, DOOR MIRROR, OTR LH	Not Necessary	138.00 FL	*- FL
66	1		*COVER, DOOR MIRROR, OTR, LH	Not Necessary	138.00 FL	*- FL
67	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
68	1		*PAD, FR FENDER (Supplementary)	Missing	38.00 FL	*38.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>18,899.00</b>	<b>7,861.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (\$\$)</b>	4,328.37	1,803.43
<b>Total Parts (\$\$)</b>	<b>14,570.63</b>	<b>6,057.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER, BONNET, FRT SUPPORT, LHF FENDER & LHF DOOR REPAIR LHF, WHEELHOUSE, LHF A PILLAR, LHF DOOR PILLAR & LHF CHASSIS	New	3,600.00	2,250.00
2	RESPRAY FRT BUMPER, BONNET, FRT SUPPORT, LHF FENDER, LHF WHEELHOUSE, LHF DOOR, LH WINGMIRROR, LH A PILLAR, LHF DOOR PILLAR & FRT CHASSIS	New	3,150.00	2,100.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AIRCON GAS	New	80.00	0.00
5	RENEW LHF SPORT RIM & TRANSFER TYRE	New	30.00	30.00
6	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
9	RENEW FRT U/CARRIAGE INCLUDING X-MEMBER, RACK & PINION & LHF SHOCK ABSORBER & LHF DRIVE SHAFT	New	900.00	0.00
10	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
11	SUPPLY BODY PNL SEALANT	New	80.00	60.00
			<b>Gross Labour Cost (S\$)</b>	<b>4,750.00</b>
			<b>8,290.00</b>	<b>4,750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >