



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 7666M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	DISTORTED	696.40	696.40
1	FRONT BUMPER RETAINER RH (CONSISTENT)	BENT	15.80	15.80
1	FRONT BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	15.80	-
1	FRONT BUMPER TOP RUBBER (CONSISTENT)	* CHECK	47.80	-
1	FRONT BUMPER FOGLAMP ASSEMBLY RH (CONSISTENT)	* CHECK	645.60	-
1	HEADLAMP RH (CONSISTENT)	SCRATCHED	2,772.30	2,772.30
1	FRONT FENDER RH (CONSISTENT)	BADLY DENTED	653.00	653.00
1	FRONT FENDER INNER SHIELD RH (CONSISTENT)	TORN	126.90	126.90
8	FRONT FENDER INNER SHIELD CLIP RH @\$3.50 (CONSISTENT)	NECESSARY	28.00	28.00
1	FRONT FENDER TOP CHROME RH (CONSISTENT)	NOT NECESSARY	201.50	-
1	FRONT FENDER LOWER COVER (CONSISTENT)	* CHECK	211.10	-
1	FRONT KNUCKLE ARM RH (CONSISTENT)	* CHECK	483.30	-
1	FRONT LOWER ARM RH (CONSISTENT)	* CHECK	526.90	-
1	FRONT SHOCK ABSORBER RH (CONSISTENT)	* CHECK	407.70	-
1	FRONT ABSORBER MOUNTING RH (CONSISTENT)	* CHECK	117.30	-
1	FRONT ABSORBER STOPPER RH (CONSISTENT)	* CHECK	43.40	-
1	FRONT CALIPER RH (CONSISTENT)	NOT NECESSARY	833.70	-
1	FRONT DOOR RH (CONSISTENT)	NOT NECESSARY	268.40	-
1	FRONT WHEEL BEARING RH (CONSISTENT)	* CHECK	510.50	-
1	SUPPORT PANEL (CONSISTENT)	* CHECK	907.40	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	370.40	-
1	AIR CON CONDENSER (CONSISTENT)	NOT NECESSARY	927.50	-
1	RADIATOR (CONSISTENT)	NOT NECESSARY	839.60	-
1	FRONT WIPER SPARE TANK ASSEMBLY (CONSISTENT)	* CHECK	28.70	-
1	FRONT BUMPER SPONGE (CONSISTENT)	* CHECK	113.40	-
	LESS 20% DISCOUNT		-2,358.48	-858.48
			9,433.92	3,433.92
1	FRONT WHEEL RIM RH (SN) (CONSISTENT)	CUT	1,076.70	600.00

Report Ref No. CC4/ASM21000143/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-215.34	-
			861.36	600.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE RH (SN) (CONSISTENT)	SERVICEABLE	480.00	-
1	RADIATOR COOLANT (SN) (CONSISTENT)	NOT NECESSARY	150.00	-
			630.00	-
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.		700.00	400.00
	SPRAY PAINT ON THE AFFECTED AREAS.		700.00	400.00
	ANTI-RUST COATING.		120.00	30.00
	TO REMOVE & REFIT UNDERCARRIAGE .		350.00	150.00
	FOUR WHEEL ALIGNMENT.		180.00	60.00
	WIRING .		40.00	20.00
	TO SERVICE & TOP-UP AIR-CON GAS.	NOT NECESSARY	180.00	-
			2,270.00	1,060.00
GRAND TOTAL			13,195.28	5,093.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,508.56 NETT)				4,050.00

Report Ref No. CC4/ASM21000143/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.