



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Ref: CC4/ASM21000143/Upa3q2
Date: 01/02/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8812K	Veh. Inspected	SKQ 7666M
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S1M02ZSZ	Excess (\$)	0.00
Assign From		Assign Date	05/01/2021

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA (A)	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHE341CMFA066711	Colour	SILVER
Odometer	66321 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45Z R18	MICHELIN	8 mm
L/H Front Tyre	225/45Z R18	MICHELIN	8 mm
R/H Rear Tyre	225/45Z R18	MICHELIN	8 mm
L/H Rear Tyre	225/45Z R18	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/01/2021	Inspection Date	05/01/2021
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**