

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000144/UQD3E2

Date: 12/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100345904-07
Claimant Vehicle No : SMN9775K **Insured Vehicle No :** SKK2917D
Date of Loss: 30/12/2020 Nature of Claim: TP Claim No: 1757209248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN9775K**
Make & Model: HONDA FREED, 1.5 (A) Engine No: LEB5611838
Reg. Date: 04/09/2019 (Man. Year: 2018) Chassis No: GB71076423
Colour: Green Odometer: 60769 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 5,299.96 | 2,296.32 | 3,003.64 | 56.67 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,040.00 | 1,710.00 | 1,330.00 | 43.75 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,339.96 | 4,006.32 | 4,333.64 | 51.96 |
| Approved Total (Overridden) (S\$) | | 3,200.00 | | |
| (S\$) | 8,339.96 | 3,200.00 | 5,139.96 | 61.63 |
| + GST 7.00/7.00% (S\$) | 583.80 | 224.00 | 359.80 | 61.63 |
| Nett Amount (S\$) | 8,923.76 | 3,424.00 | 5,499.76 | 61.63 |

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 09/03/2021 Inspected At:

Estimated Period of Repair: 4.0 days

Bluwel Automotive Service Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
Autobay@Kaki Bukit
Singapore 417883

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------|---------------|--|-------------------|
| 1 | 1 | | *REAR TAILGATE | Dented / Bent | 1,984.80 FL | *1,285.00 FL |
| 2 | 1 | | *REAR TAILGATE INNER BOARD | Not Necessary | 288.40 FL | *- FL |
| 3 | 1 | | *REAR TAILGATE LOCK | Not Necessary | 157.20 FL | *- FL |
| 4 | 1 | | *REAR TAILGATE LOGO | Necessary | 32.50 FL | *32.50 FL |
| 5 | 1 | | *REAR TAILGATE RUBBER | Not Necessary | 168.40 FL | *- FL |
| 6 | 1 | | *REAR TAILGATE FREED EMBLEM | Necessary | 55.40 FL | *55.40 FL |
| 7 | 1 | | *REAR TAILGATE HYBRID EMBLEM | Necessary | 51.60 FL | *51.60 FL |
| 8 | 1 | | *REAR O/S TAILLAMP | Not Necessary | 580.40 FL | *- FL |
| 9 | 1 | | *REAR END PANEL | Repair | 623.70 FL | *- FL |
| 10 | 1 | | *REAR END PANEL INNER GARNISH | Not Necessary | 115.40 FL | *- FL |
| 11 | 1 | | *REAR BUMPER | Deformed | 925.40 FL | *925.40 FL |
| 12 | 1 | | *REAR BUMPER O/S SIDE BRACKET | Bent | 30.00 FL | *30.00 FL |
| 13 | 1 | | *REAR BUMPER O/S REFLECTOR | Cracked | 64.00 FL | *64.00 FL |
| 14 | 1 | | *REAR BUMPER SIDE RETAINERS | O/S Bent | 72.00 FL | *36.00 FL |
| 15 | 1 | | *REAR O/S FENDER | Repair | 904.00 FL | *- FL |
| 16 | 1 | | *REAR O/S FENDER AIR GATE | Cracked | 40.50 FL | *40.50 FL |
| 17 | 1 | | *REAR WINDSCREEN SEAL | Necessary | 85.00 FS | *40.00 FS |
| 18 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 60.00 FS | *40.00 FS |
| 19 | 1 | | *SET REAR REVERSE SENSOR | Shorted | 280.00 FS | *200.00 FS |
| | | | | | Sub Total (S\$) | 6,518.70 2,800.40 |
| | | | | | - List Item Discount on L Items 20.00/20.00% (S\$) | 1,218.74 504.08 |
| | | | | | Total Parts (S\$) | 5,299.96 2,296.32 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING | New | 50.00 | 30.00 |
| 2 | TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS | New | 120.00 | 80.00 |
| 3 | TO REMOVE AND REFIT REAR BUMPER SENSOR | New | 120.00 | 50.00 |
| 4 | TO REMOVE AND REFIT REAR WINDSCREEN GLASS | New | 200.00 | 120.00 |
| 5 | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS | New | 1,200.00 | 600.00 |
| 6 | TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION | New | 150.00 | 30.00 |
| 7 | TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE | New | 1,200.00 | 800.00 |
| Gross Labour Cost (\$\$) | | | 3,040.00 | 1,710.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >