

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000148/KBA3Q2
Date: 02/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070134781
Claimant Vehicle No :	SLX531R	Insured Vehicle No :	EB120S
Date of Loss:	28/12/2020	Nature of Claim:	TP
		Claim No:	4502490870SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX531R	Engine No:	PE21020626
Make & Model:	MAZDA 6, 2.0 SEDAN STANDARD EU6 (A)	Chassis No:	JM6GL1071J0135311
Reg. Date:	14/03/2018 (Man. Year: 2017)	Odometer:	75232 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 3 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,877.22	3,118.40	1,758.82	36.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	880.00	820.00	48.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,577.22	3,998.40	2,578.82	39.21
+ GST 7.00/7.00% (S\$)	460.41	279.89	180.52	39.21

Nett Amount (S\$)	7,037.63	4,278.29	2,759.34	39.21
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,680.29		

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 31/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cracked	963.50 FL	*963.50 FL
2	1		*FRONT BUMPER	Buckled / Cracked	1,151.30 FL	*1,151.30 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	14.70 FL	*14.70 FL
4	15		*FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
5	1		*FRONT FENDER LH	Bent	383.70 FL	*383.70 FL
6	1		*FRONT FENDER COWLING LH	Cracked	102.90 FL	*102.90 FL
7	1		*FRONT FENDER COWLING CLIPS (NPA)		-	-
8	1		*FRONT FENDER BRACKET LH (NPA)	Repair	0.00 FL	*- FL
9	8		*FRONT FENDER COWLING CLIPS	Necessary	24.00 FL	*24.00 FL
10	1		*FRONT WHEEL BEARING W HUB LH	Not Necessary	566.70 FL	*- FL
11	1		*FRONT KNUCKLE ARM LH	Serviceable	407.10 FL	*- FL
12	1		*FRONT LOWER ARM LH	Serviceable	259.10 FL	*- FL
13	1		*FRONT SHOCK ABSORBER LH	Serviceable	301.20 FL	*- FL
14	1		*FRONT SHOCK ABSORBER TOP MOUNTING LH	Serviceable	96.50 FL	*- FL
15	1		*FRONT STABILIZER LINKAGE LH	Serviceable	70.80 FL	*- FL
16	1		*SPORT RIM LHF	Dented	1,197.70 FS	*800.00 FS
17	1		*TYRE LHF (NPA)	Serviceable	0.00 FS	*- FS
18	1		*HARNESS BRACKET	Bent	15.40 FL	*15.40 FL
19	1		*REINFORCEMENT FRONT GRILLE	Bent	142.50 FL	*142.50 FL
20	1		*STAY FRONT FENDER FRONT LH	Bent	55.00 FL	*55.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,797.10	3,698.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	919.88	579.60
Total Parts (\$\$)	4,877.22	3,118.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	60.00
3	TO DISMANTLE ,REPLACE AND REINSTALL ALL UNDERCARRIAGE	New	280.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD .TO KNOCK & REPAIR FRONT BONNET INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	600.00	400.00
5	TO SPRAY FRONT BONNET ,FRONT BUMPER ,FRONT FENDER LH FRONT DOOR LH	New	700.00	400.00
Gross Labour Cost (\$)			1,700.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >