

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. 4987S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DENTED / BENT	2,800.00	2,130.00
1	FRONT TOP CORNER GARNISH N/S	TO REPAIR SEE LABOUR	495.00	-
1	FRONT BUMPER SIDE BLACK GARNISH N/S	DISTORTED	166.00	95.00
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	4,800.00	-
1	FRONT DOOR LOWER OUTER PROTECTOR N/S	WARPED / CRACKED	1,250.00	485.00
1	FRONT DOOR LOWER OUTER PROTECTOR INNER BRACKET N/S	BENT	620.00	300.00
1	FRONT DOOR LOWER INNER GARNISH N/S	WARPED / CRACKED	588.00	420.00
1	FRONT STEP PANEL (ALUMINIUM) N/S	CUT	692.00	390.00
1	FRONT STEP PANEL OUTER GARNISH N/S	WARPED / CRACKED	1,850.00	840.00
1	FRONT STEP PANEL REFLECTOR N/S	SCRATCHED	68.00	50.00
1	HEADLAMP N/S	CRACKED	3,200.00	2,205.00
1	FRONT STEP PANEL TOP GARNISH N/S	WARPED / CRACKED	1,820.00	1,245.00
1	FRONT WHEEL ARCH GARNISH N/S	SERVICEABLE	485.00	-
	LESS 10% DISCOUNT		-	-816.00
			18,834.00	7,344.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO RESET & REPROGRAMME SYSTEM.		250.00	100.00
	LABOUR & PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT TOP CORNER GARNISH N/S AND FRONT DOOR N/S.		800.00	540.00
	TO PUTTY & SPRAY PAINTING.		1,300.00	750.00
			2,480.00	1,410.00
	GRAND TOTAL		21,314.00	8,754.00

Report Ref No. CS/SMO21000150/Uqd3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		7,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO21000150/Uqd3e2

CHUA KANG SENG
Licensed Appraiser