

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120**Our File No:** CS/AIG21000152/EQD3Q2**Date:** 19/02/2021**REFERENCE**

Insured/Claimant:	CHANG SER SAN	Policy No:	1900246607
Date of Loss:	05/01/2021	Nature of Claim:	OD
		Claim No:	1703148809SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR526B	Engine No:	3A92UHX6618
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH002544
Reg. Date:	17/12/2019 (Man. Year: 2019)	Odometer:	5987 km
Colour:	Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,076.83	2,426.82	4,650.01	65.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,375.00	6,330.00	3,045.00	32.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,451.83	8,756.82	7,695.01	46.77
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	15,651.83	7,956.82	7,695.01	49.16
+ GST 7.00/7.00% (S\$)	1,095.63	556.98	538.65	49.16
Nett Amount (S\$)	16,747.46	8,513.80	8,233.66	49.16

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 05/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 13.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL,RR END	Dented	425.00 FL	*425.00 FL
2	1		*PANEL,QTR,OTR LH	Dented	755.00 FL	*755.00 FL
3	1		*PANEL,RR COMB LAMP HSG,LH	Dented	60.00 FL	*60.00 FL
4	1		*EXTN,QTR PANEL,UPR OTR LH	Not Necessary	118.00 FL	*- FL
5	1		*REINF,RR PILLAR,LH	Not Necessary	126.00 FL	*- FL
6	1		*PANEL QTR,LWR INR LH	Not Necessary	228.00 FL	*- FL
7	1		*LID,FUEL FILLER	Repair	48.00 FL	*- FL
8	1		*CLIP,FUEL FILLER LID LOCKI	Necessary	3.00 FL	*3.00 FL
9	1		*GLASS,RR WINDOW	Not Necessary	544.00 FL	*- FL
10	2		*STOPPER,WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
11	3		*SPACER,RR WINDOW	Necessary	27.00 FL	*27.00 FL
12	1		*LAMP ASSY,COMB,RR LH	Broken	335.00 FL	*335.00 FL
13	2		*GROMMET,TAIL LAMP	Necessary	6.00 FL	*6.00 FL
14	2		*GROMMET,TAIL LAMP	Necessary	6.00 FL	*6.00 FL
15	1		*LH REFLECTOR	Not Necessary	23.00 FL	*- FL
16	1		*TRIM,RR END	Not Necessary	66.00 FL	*- FL
17	1		*TRIM,TRUNK ROOM SIDE,LH	Crushed	160.00 FL	*160.00 FL
18	1		*MARK,THREE-DIA	Necessary	69.00 FL	*69.00 FL
19	1		*MARK,ATTRAGE	Necessary	21.00 FL	*21.00 FL
20	1		*WEATHERSTRIP,TRUNK LID	Crushed	157.00 FL	*157.00 FL
21	1		*STRIKER,TRUNK LID LATCH	Not Necessary	20.00 FL	*- FL
22	1		*LATCH,TRUNK LID	Not Necessary	218.00 FL	*- FL
23	1		*BRACKET,RR BUMPER,LH	Broken	28.00 FL	*28.00 FL
24	1		*BRACKET,RR BUMPER,RH	Not Necessary	28.00 FL	*- FL
25	6		*CLIP,FR BUMPER	Necessary	24.00 FL	*24.00 FL
26	1		*FACE,RR BUMPER	Broken	748.00 FL	*748.00 FL
27	1		*WHEEL,DISC	Not Necessary	687.00 FL	*- FL
28	1		*DRUM ASSY,RR BRAKE	Not Necessary	259.00 FL	*- FL
29	1		*DECAL,MIVEC	Necessary	36.00 FL	*36.00 FL
30	1		*ATTRAGE BODYKITS	Not Necessary	1,643.00 FS	*- FS
31	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
33	1		*BODY SEALANT	Necessary	160.00 FS	*80.00 FS
34	1		*LH REAR TIRES	Not Necessary	280.00 FS	*- FS
35	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
36	1		*PARKING SENSOR	Not Necessary	220.00 FS	*- FS
37	1		*REAR BUMPER (Supplementary)	Repeated	748.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,452.00	3,086.00
- List Item Discount on L Items 23.00/23.00% (\$)	1,375.17	659.18
Total Parts (\$)	7,076.83	2,426.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER,CUT/WELD LH REAR FENDER,LH TAILAMP HOUSING,REAR END PANEL,REPAIR LH REAR DOOR,REMOVE AND INSTALL LH SKIRTING TO FACILITATE REPAIR WORK	New	3,600.00	2,250.00
2	REMOVE AND REPLACE REAR WINDSCREEN (CUT SCRATCHES LINE)	New	240.00	240.00
3	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK	New	120.00	120.00
4	REMOVE AND INSTALL REAR PARKING ASSIST	New	60.00	60.00
5	REPLACE REAR WINDSCREEN SOLAR FILM	New	220.00	0.00
6	PAINT WORK SPRAY REAR END PANEL,REAR BUMPER,REAR BODY KITS,LH REAR FENDER,FUEL CAP COVER,LH REAR DOOR,REAR TAILAMP HOUSING,REAR SPOILER LIP AND AFFECTED PORTION	New	3,150.00	2,275.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	LABOUR RENEW SPORT RIM INCLUDING BALANCING	New	30.00	0.00
10	PERFORM RUST PREVENTION	New	160.00	40.00
11	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
12	REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK	New	450.00	450.00
13	TO RENEW REAR U/CARRIAGE DAMAGES	New	450.00	0.00
14	RESPRAY IN THE FENDER (Supplementary)	New	175.00	175.00
15	REPAIR INNER PANEL & REAR END PANEL (Supplementary)	New	450.00	450.00
Gross Labour Cost (\$\$)			9,375.00	6,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >