



CYCLE & CARRIAGE

ATG - OD CLAIM
SURVEY: 05/01/21
LKK - STEVE

VEHICLE NO : SMR 526 B

MODEL : MIT/ATRAGE 1.2 CVT

WIP : 61481

Material	:	\$	<u>2,206.82</u>
Labour	:	\$	<u>6,550.00</u>
Sub-Total	:	\$	<u>8,756.82</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>800.00</u>
Total	:	\$	<u>7,956.82</u>
GST 7%	:	\$	<u>556.98</u>
Grand Total	:	\$	<u>8,513.80</u>
Finalise By/Date	:	<u>WIP on 01/02/21</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 13 WORKING DAYS + 6 days (3 wk. ends)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 07/01/2021	Cust No/Name	/CHANG SER SAN
	Reg No/Reg Date	SMR526B / 17/12/2019
	Date In/Mileage	07/01/2021/ 5987
	Chassis/Package	MMBSTA13AKH002544 /DC17P
	Engine No	3A92UHX6618
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	01/02/2021/ 14:03	BLD	884 / Lauro Songcuan	61481				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E	PNT88000	RENEW DAMAGED PARTS ON REAR BUMPER, CUT/WELD LH REAR FENDER, LH TAILAMP HOUSING, REAR END PANEL, REPAIR LH REAR DOOR, REMOVE AND INSTALL LH SKIRTING TO FACILITATE REPAIR							2250.00 ✓
E	PNT88000	REMOVE AND INSTALL REAR WINDSCREEN GLASS							240.00 ✓
M	SUNDRY	SUPPLY REAR WINDSCREEN SEALANT							80.00 ✓
E	PNT88000	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR							120.00 ✓
E	PNT88000	REMOVE AND INSTALL REAR PARKING ASSIST							60.00 ✓
E	PNT98000	SPRAY PAINT REAR END PANEL, REAR BUMPER, REAR BOOT LID, REAR BODY KITS, LH REAR FENDER, FUEL CAP COVER, LH REAR DOOR, REAR TAILAMP HOUSING, REAR SPOILER LIP AND AFFECTED PORTIONS							2275.00 ✓
M	SUNDRY	APPLY BODY SEALANT ON AFFECTED AREAS							80.00 ✓
A	54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00 ✓
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00 ✓
M	SUNDRY	PERFORM RUST PREVENTION ON AFFECTED PORTIONS							40.00 ✓
A	WHEELALIGNMENTBP	To Conduct Computerize Full Wheel Alignment							120.00 ✓
A	13900099	REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR							450.00 ✓
M	SUNDRY	SUPPLY C&C LOGO							40.00 ✓
M	SUNDRY	SUNDRIES							20.00 ✓

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 07/01/2021	Cust No/Name	/CHANG SER SAN
	Reg No/Reg Date	SMR526B / 17/12/2019
	Date In/Mileage	07/01/2021/ 5987
	Chassis/Package	MMBSTA13AKH002544 /DC17P
	Engine No	3A92UHX6618
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	01/02/2021/ 14:03	BLD	884 / Lauro Songcuan	61481

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X-EXC				-800.00
INSURANCE EXCESS				
E PNT88000				450.00 X
REPAIR INNER FENDER → <i>supp</i>				
E PNT98000				175.00 X
SPRAY PAINT INNER FENDER → <i>supp</i>				
X PANEL,RR END X	1.00	425.00	23.00	327.25 ?
X PANEL,QTR,OTR LH ✓	1.00	755.00	23.00	581.35 ✓
X PANEL,RR COMB LAMP HSG,LH ✓	1.00	60.00	23.00	46.20 ✓
X CLIP,FUEL FILLER LID LOCKI ✓	1.00	3.00	23.00	2.31 ✓
X STOPPER,WINDSHIELD GLASS ✓	2.00	3.00	23.00	4.62 ✓
X SPACER,RR WINDOW ✓	3.00	9.00	23.00	20.79 ✓
X LAMP ASSY,COMB,RR LH ✓	1.00	335.00	23.00	257.95 ✓
X GROMMET,TAIL LAMP ✓	2.00	3.00	23.00	4.62 ✓
X GROMMET,TAIL LAMP ✓	2.00	3.00	23.00	4.62 ✓
X TRIM,TRUNK ROOM SIDE,LH ✓	1.00	160.00	23.00	123.20 ✓
X MARK,THREE-DIA ✓	1.00	69.00	23.00	53.13 ✓
X MARK,ATTRAGE ✓	1.00	21.00	23.00	16.17 ✓
X WEATHERSTRIP,TRUNK LID ✓	1.00	157.00	23.00	120.89 ✓
X BRACKET,RR BUMPER,LH ✓	1.00	28.00	23.00	21.56 ✓
X CLIP,FR BUMPER ✓	6.00	4.00	23.00	18.48 ✓
X FACE,RR BUMPER ✓	1.00	748.00	23.00	575.96 ✓
X DECAL,MIVEC ✓	1.00	36.00	23.00	27.72 ✓
Z TEXT				
OD CLAIM - AIG				
DOA: 05.01.2021				
SURVEY: STEVE (LKK) 05.01.2020				
13 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,206.82			
Labour	6,290.00			
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	-540.00			
Total(w/o GST)	7,956.82			
		7% GST on	7956.82	556.98
		Total Payable		8,513.80

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMR 526 B**

	<u>Labour</u>		<u>Cost \$</u>
1	Repair Inner Fender		450.00 ✓
2	Spray Paint Inner Fender		175.00 ✓
			<u>625.00</u>
		7% GST	43.75
		Total	<u>668.75</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMRS268B

WIP: 61481

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Rear Bumper	? / SUPP		✓	\$575.96
2	rear and fan	? / SUPP		✓	\$327.25
3	respray in the fender	? / SUPP		✓	
4	Remove and install Petrol tank	? / SUPP			Steve
5		? / SUPP			
6	repair ↓ Day	? / SUPP		✓	13/1/21
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	18/1/21	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Attrage 1.2

SURVEYOR: Steve @ LK

Work Order: R001326
License: SMR526B
Technician: ALVIN(108)
Mileage: 5987
Date: 26.1.21 12:09

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°33'	-0°32'	-0°40' 0°50'
4°03'	4°04'	3°15' 4°45'
0°00'	-0°09'*	-0°07' 0°07'
14°05'*	14°06'*	10°05' 13°05'
13°32'	13°33'	9°25' 13°55'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°35'	-0°35'	-0°40' 0°50'
4°42'	4°44'	3°15' 4°45'
0°01'	0°00'	-0°07' 0°07'
13°48'*	13°49'*	10°05' 13°05'
13°13'	13°15'	9°25' 13°55'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°02'	0°02'	-0°30' 0°30'
-0°39'*	-0°40'*	-0°30' 0°30'
0°17'	0°17'	
0°01'	-0°08'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°47'	-0°48'	-1°45' -0°15'
0°06'	0°06'	-0°01' 0°13'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°12'	-1°12'	-1°45' -0°15'
0°11'	0°11'	-0°01' 0°13'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°25'	0°24'	-0°30' 0°30'
0°17'	0°17'	-0°02' 0°26'
-0°03'	-0°03'	

Work Order: R001326
License: SMR526B
Technician: ALVIN(108)
Mileage: 5987
Date: 26.1.21 12:09

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°33'	-0°32'	-0°40' 0°50'
4°03'	4°04'	3°15' 4°45'
0°00'	-0°09**	-0°07' 0°07'
14°05**	14°06**	10°05' 13°05'
13°32'	13°33'	9°25' 13°55'

Front : Right

Actual	Before	Specified Range
-0°35'	-0°35'	-0°40' 0°50'
4°42'	4°44'	3°15' 4°45'
0°01'	0°00'	-0°07' 0°07'
13°48**	13°49**	10°05' 13°05'
13°13'	13°15'	9°25' 13°55'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°02'	0°02'	-0°30' 0°30'
-0°39**	-0°40**	-0°30' 0°30'
0°17'	0°17'	
0°01'	-0°08'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°47'	-0°48'	-1°45' -0°15'
0°06'	0°06'	-0°01' 0°13'

Rear : Right

Actual	Before	Specified Range
-1°12'	-1°12'	-1°45' -0°15'
0°11'	0°11'	-0°01' 0°13'

Camber
Toe

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°25'	0°24'	-0°30' 0°30'
0°17'	0°17'	-0°02' 0°26'
-0°03'	-0°03'	

All DTGs

Item	Setting	Information
M.U.T.-3 Version		SEW20091-00
V.C.I. Version		B178
Vehicle Information		A13A 2019MY

SMR526B

Before use, please use not to check all the found

2021.01.19

All DTCS

2021.01.19

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010	P0513	Incorrect Immobilizer key	Active
AT/CVT/A-MT/T/C-SST	KOSOSS_99880010		No DTCS	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCS	
ABS/ASC/ASTC/MSS	KOSOSS_99880010	C1371	Yaw rate SNSR:stuck/low gain	Stored
SRS-AIR BAG	KOSOSS_99880010		No DTCS	
Air Conditioner	KOSOSS_99880010		No DTCS	
ETACS	KOSOSS_99880010	B1707	Flasher open	Active
Meter	KOSOSS_99880010		No DTCS	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCS	

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW20091-00
V.C.I. Version		B178
Vehicle Information		A13A 2019MY

SMR 526B

After Repair to Car out Synthetic to Pass
 ball test sound
 2019 08 10

All DTCs

2021.01.26

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCs	
AT/CVT/A-MT/T/C-SST	KOSOSS_99880010		No DTCs	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCs	
SRS-AIR BAG	KOSOSS_99880010		No DTCs	
Air Conditioner	KOSOSS_99880010		No DTCs	
ETACS	KOSOSS_99880010		No DTCs	
Meter	KOSOSS_99880010		No DTCs	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCs	