

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000153/UTD3Q2

Date: 19/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00008232000

Claimant Vehicle No : SFK14G **Insured Vehicle No :** SFQ8910K

Date of Loss: 30/12/2020 Nature of Claim: TP Claim No: SNM21D200046/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFK14G**

Make & Model: AUDI A8 L, 3.0 TFSI QU (A) Engine No: CRE156293

Reg. Date: 25/08/2017 (Man. Year: 2016) Chassis No: WAUZZZ4H8HN011115

Colour: White Odometer: 39189 km

Engine Capacity: 2995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45R19	Rear Tyre Size:	255/45R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,546.94	4,163.12	18,383.82	81.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,450.00	1,480.00	4,970.00	77.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,996.94	5,643.12	23,353.82	80.54
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	28,996.94	4,500.00	24,496.94	84.48
+ GST 7.00/7.00% (S\$)	2,029.79	315.00	1,714.79	84.48
Nett Amount (S\$)	31,026.73	4,815.00	26,211.73	84.48

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 12/01/2021 Inspected At:

Kaizen Motors Pte Ltd (HQ)
68 KAKI BUKIT AVE 6, #02-12 ARK
@ KAKI BUKIT
Singapore 417896

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2021)
Parts: 143	AUDI A8 L 3.0 TFSI QU (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFK14G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR R/H DOOR ASSY	Warped	3,763.80 F	*3,149.60 FL
2	1		*REAR R/H DOOR SEAL	Necessary	259.82 F	*180.00 FL
3	2		*REAR R/H DOOR PLUG	Not Necessary	111.30 F	*- FL
4	2		*REAR R/H DOOR HINGES	Not Necessary	216.46 F	*- FL
5	1		*REAR R/H DOOR HINGE COVER CAP	Not Necessary	55.74 F	*- FL
6	1		*REAR R/H DOOR SEALING	Not Necessary	180.11 F	*- FL
7	1		*REAR R/H DOOR B PILLAR TRIM	Not Necessary	218.80 F	*- FL
8	1		*REAR R/H DEFLECTOR STRIP	Not Necessary	559.90 F	*- FL
9	3		*REAR R/H DOOR REINFORCEMENT	Not Necessary	249.00 F	*- FL
10	1		*REAR R/H DOOR DAMPENER	Not Necessary	106.83 F	*- FL
11	1		*REAR R/H DOOR HANDLE W CHROME	Not Necessary	458.86 F	*- FL
12	1		*REAR R/H DOOR PANEL INSULATOR FILM	Not Necessary	81.78 F	*- FL
13	1		*REAR R/H DOOR PANEL INNER	Not Necessary	1,992.83 F	*- FL
14	1		*FRONT R/H DOOR ASSY	Repair	3,656.30 F	*- FL
15	1		*FRONT R/H DOOR SEAL	Not Necessary	259.82 F	*- FL
16	2		*FRONT R/H DOOR PLUG	Not Necessary	111.30 F	*- FL
17	2		*FRONT R/H DOOR HINGES	Not Necessary	216.46 F	*- FL
18	1		*FRONT R/H DOOR HINGE COVER CAP	Not Necessary	55.74 F	*- FL
19	1		*FRONT R/H DOOR SEALING	Not Necessary	180.11 F	*- FL
20	1		*FRONT R/H DOOR B PILLAR TRIM	Not Necessary	200.06 F	*- FL
21	1		*FRONT R/H DEFLECTOR STRIP	Not Necessary	559.90 F	*- FL
22	3		*FRONT R/H DOOR REINFORCEMENT	Not Necessary	249.00 F	*- FL
23	1		*REAR R/H DOOR DAMPENER	Not Necessary	106.83 F	*- FL
24	1		*FRONT R/H DOOR HANDLE W CHROME	Not Necessary	458.86 F	*- FL
25	1		*FRONT R/H DOOR PANEL INSULATOR FILM	Not Necessary	81.78 F	*- FL
26	1		*FRONT R/H DOOR PANEL INNER	Not Necessary	1,992.83 F	*- FL
27	1		*REAR R/H FENDER	Repair	3,900.54 F	*- FL
28	1		*REAR R/H TIRE	Serviceable	400.00 FS	*- FS
29	1		*REAR R/H RIM	Bent/Warped	1,562.18 FS	*1,000.00 FS
30	10		*REAR R/H DOOR HINGE SCREW	Not Necessary	100.00 FS	*- FS
31	10		*REAR R/H DOOR MOUNTING CLIP	Not Necessary	100.00 FS	*- FS
32	10		*FRONT R/H DOOR MOUNTING CLIP	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,546.94	4,329.60
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	166.48
Total Parts (\$)	22,546.94	4,163.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR CHECKING ON WIRING	New	250.00	0.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING WELDING,KNOCKING,REPAIRING,STRAIGHTENING,RESHAPE & ADJUSTMENT OF FRONT/REAR R/H DOOR ASSY & PARTS	New	2,800.00	600.00
3	SPRAYPAINTING & PUTTY OF FRONT R/H DOOR,SIDE MOULDING,FENDER,REAR R/H DOOR	New	2,600.00	800.00
4	LABOUR FOR RETROFITTING MOULDING & SEAL	New	550.00	0.00
5	WHEEL ALIGNMENT	New	250.00	80.00
Gross Labour Cost (S\$)			6,450.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >