

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000155/EQD3E2

Date: 26/01/2021

REFERENCE

Insured/Claimant: CHIEW AI JUAN Policy No:
Date of Loss: 05/01/2021 Nature of Claim: OD Claim No: 5642301637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ7715T**
Make & Model: KIA STONIC, 998cc (A) Engine No: G3LCJP143385
Reg. Date: 20/03/2019 (Man. Year: 2018) Chassis No: KNAD6811VK6244907
Colour: White Odometer: 24554 km
Engine Capacity: 998 cc
Market Value/New Car Price: S\$73,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm
Front Right Side: Kumho 5 mm Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,743.00	3,995.20	1,747.80	30.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	2,400.00	580.00	19.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,723.00	6,395.20	2,327.80	26.69
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,123.00	5,795.20	2,327.80	28.66
+ GST 7.00/7.00% (S\$)	568.61	405.66	162.95	28.66
Nett Amount (S\$)	8,691.61	6,200.86	2,490.75	28.66

INSPECTION

Date of Assignment: 05/01/2021
Date Inspected: 05/01/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER UPR	Broken	476.00 F	*476.00 FL
2	1		*SKID PLATE-FR BUMPER	Not Necessary	55.00 F	*- FL
3	1		*LIP ASSY-FRONT BUMPER	Not Necessary	32.00 F	*- FL
4	1		*COVER-RADIATOR GRILLE UPR	Crushed	46.00 F	*46.00 FL
5	1		*COVER-FR BUMPER FOG LAMP,RH	Cut	64.00 F	*64.00 FL
6	1		*LAMP ASSY-FRONT FOG,RH	Broken	234.00 F	*234.00 FL
7	1		*AIR DUCT-FR BUMPER,RH	Broken	38.00 F	*38.00 FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	98.00 F	*98.00 FL
9	1		*BRACKET-FR BUMPER SIDE,RH	Broken	13.00 F	*13.00 FL
10	1		*COVER-FR BUMPER,LWR	Cut	367.00 F	*367.00 FL
11	1		*STIFFNER-FR BPR LWR	Not Necessary	123.00 F	*- FL
12	1		*PANEL ASSY-HOOD	Dented	904.00 F	*904.00 FL
13	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	544.00 F	*- FL
14	1		*CARRIER ASSY-FRONT END MODULE	Crushed	556.00 F	*556.00 FL
15	1		*ORNAMENT-KIA NO 115	Necessary	32.00 F	*32.00 FL
16	1		*GUARD ASSY-FRONT WHEEL,RH	Torn	56.00 F	*56.00 FL
17	1		*RESERVOIR & PUMP ASSY-WASHER	Broken	152.00 F	*152.00 FL
18	1		*LAMP ASSY-HEAD,RH	Broken	1,845.00 F	*1,845.00 FL
19	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
20	10		*CLIPS (Supplementary)	Necessary	10.00 F	*10.00 FL
21	2		*NUTS (Supplementary)	Necessary	4.00 F	*4.00 FL
22	2		*RETAINER (Supplementary)	Necessary	2.00 F	*2.00 FL
23	2		*CLIPS (Supplementary)	Necessary	6.00 F	*6.00 FL
24	1		*MOULDING-FRONT BUMPER A/INTAKE (Supplementary)	Crushed	61.00 F	*61.00 FL
25	1		*CAP-FRONT HOOK (Supplementary)	Crushed	5.00 F	*5.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,743.00	4,989.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	993.80
Total Parts (S\$)	5,743.00	3,995.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER,BONNET,FRT SUPPORT PANEL,REPAIR FRT FENDER RH	New	1,600.00	1,200.00
2	SPRAY PAINT FOR FRT BUMPER,BONNET,FRT FENDER RH	New	1,050.00	1,050.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	0.00
6	TO UP AIRCON GAS	New	80.00	0.00
Gross Labour Cost (S\$)			2,980.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >