

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000158/UBA3Q2
Date: 23/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070156249
Claimant Vehicle No :	GBD7431Z	Insured Vehicle No :	YP644L
Date of Loss:	04/01/2021	Nature of Claim:	TP
		Claim No:	5221594192SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD7431Z		
Make & Model:	NISSAN NV200, 1.6 DX (A)	Engine No:	HR16007729D
Reg. Date:	21/04/2015 (Man. Year: 2014)	Chassis No:	VM20060111
Colour:	White	Odometer:	142803 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,197.00	4,758.79	10,438.21	68.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,760.00	1,370.00	43.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,327.00	6,518.79	11,808.21	64.43
Approved Total (Overridden) (S\$)		5,200.00		

(S\$)	18,327.00	5,200.00	13,127.00	71.63
+ GST 7.00/7.00% (S\$)	1,282.89	364.00	918.89	71.63
Nett Amount (S\$)	19,609.89	5,564.00	14,045.89	71.63
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,166.00		
Global Sum Settlement (S\$)		6,100.00		

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 05/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	988.60 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	110.10 F	*66.80 FL
3	1		*TAILGATE	Dented / Warped	2,245.20 F	*1,845.20 FL
4	1		*TAILGATE REAR LOGO	Necessary	105.00 F	*79.90 FL
5	1		*TAILGATE NV 200 EMBLEM	Necessary	98.00 F	*98.00 FL
6	1		*TAILGATE VANETTE EMBLEM	Necessary	102.00 F	*98.00 FL
7	1		*TAILGATE 600KG STICKER	Not Necessary	80.00 F	*- FL
8	1		*TAILGATE INNER TRIM	Deformed / Torn	485.00 F	*248.20 FL
9	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	50.00 F	*35.00 FL
10	1		*TAILGATE INNER LOCK	Dented/ Shorted	399.20 F	*135.20 FL
11	1		*TAILGATE WEATHERSTRIP	Not Necessary	388.50 F	*- FL
12	1		*TAILGATE LOCK STRIKER	Not Necessary	60.00 F	*- FL
13	2		*TAILGATE DAMPERS	Not Necessary	640.00 F	*- FL
14	1		*TAILGATE INNER CLOSING HANDLE	Not Necessary	65.00 F	*- FL
15	1		*TAILGATE OUTER HANDLE GARNISH	Grazed	362.00 F	*299.20 FL
16	1		*REAR BUMPER	Deformed	699.20 F	*632.00 FL
17	1		*REAR BUMPER SPONGE	Torn	254.00 F	*194.20 FL
18	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	110.00 F	*- FL
19	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
20	1		*REAR END PANEL OUTER	Badly Dented	699.20 F	*699.20 FL
21	1		*REAR END PANEL INNER	Repair	895.00 F	*- FL
22	1		*REAR END PANEL TOP GARNISH	Not Necessary	222.00 F	*- FL
23	1		*REAR FLOOR PANEL	Repair	1,660.00 F	*- FL
24	1		*REAR FLOOR PANEL TOP CARPER	Not Necessary	659.00 F	*- FL
25	1		*TAILLAMPS	N/S Cracked	960.00 F	*277.20 FL
26	2		*TAILLAMP HOUSING PANELS	Repair	1,372.00 F	*- FL
27	1		*REAR EXHAUST	Not Necessary	688.00 F	*- FL
28	1		*REAR EXHAUST MOUNTING	Not Necessary	35.00 F	*- FL
29	1		*SET 5 PAX & 70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
30	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
33	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1		*SET REAR CARPORATE STICKER	Necessary	280.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	15,197.00	5,233.10
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	474.31
					Total Parts (S\$)	15,197.00	4,758.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACED REAR WINDSCREEN	New	150.00	120.00
4	TO SPRAY RUST PROOFING	New	150.00	60.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	800.00
6	TO PUTTY & SPRAY PAINTING	New	1,200.00	700.00
Gross Labour Cost (S\$)			3,130.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >