

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21000160/KBA3Q2
Date: 30/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700018100
Claimant Vehicle No :	SHC5970G	Insured Vehicle No :	SLP7685B
Date of Loss:	31/12/2020	Nature of Claim:	TP
		Claim No:	1224270391SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5970G		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002441
Reg. Date:	18/12/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC280989
Colour:	Metallic White/Red	Odometer:	532815 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,623.76	1,008.24	1,615.52	61.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,070.00	480.00	6,590.00	93.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,693.76	1,488.24	8,205.52	84.65
Approved Total (Overridden) (S\$)		1,200.00		

(S\$)	9,693.76	1,200.00	8,493.76	87.62
+ GST 7.00/7.00% (S\$)	678.56	84.00	594.56	87.62
Nett Amount (S\$)	10,372.32	1,284.00	9,088.32	87.62
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$81.13/day) (S\$)		405.65		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,947.14		
Global Sum Settlement (S\$)		1,940.00		

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 04/01/2021

Estimated Period of Repair: 1.5 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPE LOWER REAR	Dented / Cut	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
5	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
6	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
7	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
8	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
9	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
10	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
11	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
12	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
13	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
14	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
15	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
					Sub Total (\$\$)	2,813.40
					- List Item Discount on L Items 10.00/10.00% (\$\$)	189.64
					Total Parts (\$\$)	2,623.76
						1,008.24

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (\$\$)			7,070.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >