

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000162/GQD3E2

Date: 29/01/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800116258
Claimant Vehicle No :	SGS8697D	Insured Vehicle No :	SKJ211A
Date of Loss:	03/01/2021	Nature of Claim:	TP
		Claim No:	5439904039SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS8697D	Engine No:	Z6517375
Make & Model:	MAZDA 3, 1.6 (A)	Chassis No:	JM6BK106270330324
Reg. Date:	27/03/2007 (Man. Year: 2006)	Odometer:	190092 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	RADAR 6 mm	Rear Left Side:	RADAR 6 mm
Front Right Side:	RADAR 6 mm	Rear Right Side:	RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	05/01/2021	
Date Inspected:	18/01/2021 Inspected At:	Hock Motors Workshop (HQ) NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER LOWER SPOILER	Cut	0.00 F	*- F
5	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
6	1		*ENGINE UNDER COVER	Cracked	0.00 F	*- F
7	1		*FRT LH FENDER	Buckled	0.00 F	*- F
8	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
9	1		*FRT LH WHEEL RIM	Repair	0.00 F	*- F
10	1		*FRT LH DOOR	Repair	0.00 F	*- F
11	1		*FRT LH DOOR PROTECTOR	Cut	0.00 F	*- F
12	1		*ROCKER PANEL OUTER SIDE SKIRT LH	Repair	0.00 F	*- F
13	1		*REAR LH DOOR	Repair	0.00 F	*- F
14	1		*REAR LH DOOR PROTECTOR	Scratched	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >