

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21000166/UQD3Q2

**Date:** 19/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070043598

**Claimant**  
**Vehicle No :** SLE6951Y **Insured Vehicle No :** SKE8245B

Date of Loss: 27/12/2020 Nature of Claim: TP Claim No: 4164065694SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE6951Y**  
 Make & Model: MERCEDES-BENZ A180, 1.6 FL STYLE (R17 HLG) (A) Engine No: 27091030938453  
 Reg. Date: 29/07/2016 (Man. Year: 2016) Chassis No: WDD1760422J453771  
 Colour: Blue Odometer: 93359 km  
 Engine Capacity: 1595 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24,742.00	1,539.50	23,202.50	93.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	470.00	4,930.00	91.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,142.00</b>	<b>2,009.50</b>	<b>28,132.50</b>	<b>93.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,600.00</b>		
<b>(S\$)</b>	30,142.00	1,600.00	28,542.00	94.69
<b>+ GST 7.00/7.00% (S\$)</b>	2,109.94	112.00	1,997.94	94.69
<b>Nett Amount (S\$)</b>	<b>32,251.94</b>	<b>1,712.00</b>	<b>30,539.94</b>	<b>94.69</b>

### INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 11/01/2021 Inspected At:

Kaizen Motors Pte Ltd (HQ)  
 68 KAKI BUKIT AVE 6, #02-12 ARK  
 @ KAKI BUKIT  
 Singapore 417896

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted/Cracked	1,655.00 F	*1,655.00 FL
2	1		*REAR BUMPER TOW COVER	Not Necessary	89.00 F	*- FL
3	2		*REAR BUMPER BRACKET	Not Necessary	146.00 F	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	152.00 F	*- FL
5	2		*REAR BUMPER CHROME SIDE GARNISH	Not Necessary	1,740.00 F	*- FL
6	1		*REAR BUMPER CHROME CENTER GARNISH	Not Necessary	544.00 F	*- FL
7	1		*REAR BUMPER DIFFUSER	Not Necessary	450.00 F	*- FL
8	1		*REAR REINFORCEMENT BEAM	Not Necessary	710.00 F	*- FL
9	1		*REAR BOOT	Not Necessary	2,950.00 F	*- FL
10	1		*REAR BOOT TRIMMING	Not Necessary	1,780.00 F	*- FL
11	1		*REAR END PANEL	Not Necessary	1,660.00 F	*- FL
12	1		*REAR END PANEL TRIMMING	Not Necessary	190.00 F	*- FL
13	1		*REAR SPARE TIRE WHEEL COMPARTMENT	Not Necessary	4,250.00 F	*- FL
14	2		*REAR TAIL LAMP	Not Necessary	1,660.00 F	*- FL
15	1		*REAR R/H FENDER	Not Necessary	2,980.00 F	*- FL
16	1		*REAR EXHAUST	Not Necessary	1,900.00 F	*- FL
17	1		*REAR MERCEDES EMBLEM	Not Necessary	76.00 F	*- FL
18	1		*REAR MERCEDES AMG EMBLEM	Not Necessary	210.00 F	*- FL
19	1		*REAR A180 EMBLEM	Not Necessary	110.00 F	*- FL
20	20		*REAR BUMPER CLIPS	Necessary	140.00 FS	*50.00 FS
21	10		*REAR TAIL LAMP CLIPS	Not Necessary	70.00 FS	*- FS
22	10		*REAR BUMPER DIFFUSER CLIPS	Not Necessary	70.00 FS	*- FS
23	10		*REAR BOOT TRIMMING CLIPS	Not Necessary	70.00 FS	*- FS
24	6		*REAR REVERSE SENSOR	Not Necessary	1,140.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>24,742.00</b>	<b>1,705.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>165.50</b>
<b>Total Parts (\$\$)</b>	<b>24,742.00</b>	<b>1,539.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR FOR CHECKING ON WIRING	New	250.00	20.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING WELDING,KNOCKING,REPAIRING,STRAIGHTENING,RESHAPE & ADJUSTMENT OF REAR END ASSY & PARTS	New	2,800.00	200.00
3	SPRAYPAINTING & PUTTY OF REAR BUMPER,REAR BOOT REAR DIFFUSER	New	1,800.00	250.00
4	LABOUR FOR RETROFITTING MOULDING & SEAL	New	550.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,400.00</b>	<b>470.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**