

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000167/UVD3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00011682000
Claimant Vehicle No :	SFD188A	Insured Vehicle No :	GBF8826B
Date of Loss:	02/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200037C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFD188A	Engine No:	13041518352306PS
Make & Model:	JAGUAR XJ, 2.0 TSS (A)	Chassis No:	SAJAC2284E8V63346
Reg. Date:	19/03/2015 (Man. Year: 2013)	Odometer:	90878 km
Colour:	Blue		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40ZR19	Rear Tyre Size:	275/40ZR19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,328.00	6,918.29	21,409.71	75.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,100.00	1,710.00	5,390.00	75.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,428.00	8,628.29	26,799.71	75.65
Approved Total (Overridden) (S\$)		6,900.00		
	(S\$)	35,428.00	6,900.00	28,528.00
+ GST 7.00/7.00% (S\$)	2,479.96	483.00	1,996.96	80.52
Nett Amount (S\$)	37,907.96	7,383.00	30,524.96	80.52

INSPECTION

Date of Assignment:	02/03/2021	
Date Inspected:	08/01/2021	Inspected At: Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT Singapore 417896
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
Parts:	143	JAGUAR XJ 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFD188A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR L/H DOOR ASSY	Badly Dented	4,078.00 F	*3,911.22 FL
2	1		*REAR L/H DOOR SEAL	Not Necessary	375.00 F	*- FL
3	2		*REAR L/H DOOR PLUG	Not Necessary	576.00 F	*- FL
4	2		*REAR L/H DOOR HINGES	Not Necessary	430.00 F	*- FL
5	1		*REAR L/H DOOR HNGE COVER CAP	Not Necessary	83.00 F	*- FL
6	1		*REAR L/H DOOR SEALING	Twisted	524.00 F	*282.00 FL
7	1		*REAR L/H DOOR INNER TRIM	Deformed/Twisted	961.00 F	*961.00 FL
8	1		*REAR L/H STRIP	Necessary	671.00 F	*242.62 FL
9	1		*REAR L/H DOOR REINFORCEMENT	No such part	533.00 F	*- FL
10	1		*REAR L/H DOOR GLASS CHROME MOULDING	Necessary	660.00 F	*453.20 FL
11	1		*REAR L/H DOOR DAMPENER	No such part	672.00 F	*- FL
12	1		*REAR L/H POWER WINDOW LEVER	Bent/Jammed	615.00 F	*485.00 FL
13	1		*REAR L/H POWER WINDOW SWITCH	Not Necessary	204.00 F	*- FL
14	1		*REAR L/H DOOR PANEL INSULATOR FILM	Not Necessary	345.00 F	*- FL
15	1		*REAR L/H DOOR PANEL INNER	No such part	3,031.00 F	*- FL
16	1		*REAR L/H SPEAKER	Not Necessary	630.00 F	*- FL
17	1		*REAR L/H FENDER	Repair	6,200.00 F	*- FL
18	1		*FRONT L/H DOOR ASSY	Not Necessary	5,540.00 F	*- FL
19	1		*REAR L/H TIRE	Not Necessary	600.00 FS	*- FS
20	1		*REAR L/H RIM	Cut	1,360.00 FS	*900.00 FS
21	10		*REAR L/H DOOR HINGE SCREW	Not Necessary	80.00 FS	*- FS
22	10		*REAR L/H DOOR MOUNTING CLIP	Not Necessary	80.00 FS	*- FS
23	10		*FRONT L/H DOOR MOUNTING CLIP	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,328.00	7,235.04
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	316.75
Total Parts (\$\$)	28,328.00	6,918.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR CHECKING ON WIRING	New	250.00	30.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING WELDING,KNOCKING,REPAIRING,STRAIGHTENING,RESHAPE & ADJUSTMENT OF FRONT/REAR L/H DOOR ASSY & PARTS	New	2,800.00	800.00
3	SPRAYPAINTING & PUTTY OF FRONT L/H DOOR,SIDE MOULDING,FENDER,REAR L/H DOOR	New	1,900.00	800.00
4	LABOUR FOR TRANSFERRING DOOR WINDOWS & LOCKING MECHANISM }	New	1,600.00	80.00
5	LABOUR FOR RETROFITTING MOULDING & SEAL }	New	550.00	0.00
Gross Labour Cost (S\$)			7,100.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >