

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000168/NTD3E2

Date: 02/02/2021

REFERENCE

Insured/Claimant: MOHAMMAD FAIROZ BIN MOHAMED YUSOFF
Date of Loss: 29/12/2020

Policy No: 1900159350

Nature of Claim: OD Claim No: 5549537149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN3111X**
Make & Model: YAMAHA XABRE, 150cc TFX150
Reg. Date: 06/09/2018 (Man. Year: 2017)
Colour: Silver
Engine Capacity: 150 cc
Market Value/New Car Price: S\$9,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: G3G8E0034624
Chassis No: MH3RG3710HK025617
Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 130/60 R17
Front Left Side: Zeneos 4 mm Rear Left Side: Zeneos 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,847.90	3,224.40	1,623.50	33.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	620.00	1,420.00	69.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,887.90	3,844.40	3,043.50	44.19
Approved Total (Overridden) (S\$)		3,100.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	6,587.90	2,800.00	3,787.90	57.50
+ GST 7.00/7.00% (S\$)	461.15	196.00	265.15	57.50
Nett Amount (S\$)	7,049.05	2,996.00	4,053.05	57.50

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 06/01/2021 Inspected At:

Bike Production Pte Ltd (HQ)
610 SERANGOON ROAD
Singapore 218216

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Scratched	145.00 FL	*145.00 FL
2	1		*FRONT WHEEL SHAFT	Serviceable	75.00 FL	*- FL
3	1		*LEFT FRONT FOOT REST	Bent	75.00 FL	*75.00 FL
4	1		*FRONT LEFT FORK ASSY	Serviceable	680.00 FL	*- FL
5	1		*SIDE STAND	Scratched	85.00 FL	*85.00 FL
6	1		*STEERING STEM	Bent	220.00 FL	*220.00 FL
7	1		*STEERING BRIDGE	Bent	195.00 FL	*195.00 FL
8	2		*STEERING BEARINGS	Necessary	90.00 FL	*90.00 FL
9	1		*GEAR PEDAL	Bent	78.00 FL	*78.00 FL
10	1		*FRONT LEFT SIGNAL	Missing	125.00 FL	*125.00 FL
11	1		*LEFT VIEW MIRROR	Scratched	95.00 FL	*95.00 FL
12	1		*IU BRACKET	Bent	45.00 FL	*45.00 FL
13	1		*HANDLE BAR	Bent	175.00 FL	*130.00 FL
14	1		*LEFT BALANCER	Missing	48.00 FL	*48.00 FL
15	1		*CLUTCH LEVER	Scratched	55.00 FL	*55.00 FL
16	1		*LEFT HANDGRIP	Torn	35.00 FL	*35.00 FL
17	1		*FUEL TANK LEFT COVER	Scratched	205.00 FL	*150.00 FL
18	1		*FUEL TANK AMBLEMS	Necessary	75.00 FL	*75.00 FL
19	1		*LEFT REAR SIGNAL	Scratched	115.00 FL	*115.00 FL
20	1		*LEFT SIDE COVER AMBLEM	Necessary	70.00 FL	*40.00 FL
21	1		*LEFT SIDE COVER	Cracked	175.00 FL	*140.00 FL
22	1		*SPORT RIM FRONT	Chipped	580.00 FS	*450.00 FS
23	1		*FRONT NUMBER PLATE	Bent	20.00 FS	*20.00 FS
24	1		*ERP IU	Broken	157.00 FS	*157.00 FS
25	1		*HEADLAMP ASSY (Supplementary)	Cracked	365.00 FL	*350.00 FL
26	1		*HEADLAMP BRACKET (Supplementary)	Bent	175.00 FL	*150.00 FL
27	1		*LEFT CLUTCH HOLDER (Supplementary)	Bent	75.00 FL	*75.00 FL
28	1		*CLUTCH SWITCH (SIDE STAND) (Supplementary)	Broken	65.00 FL	*65.00 FL
29	1		*LEFT SIGNAL SWITCH ASSY (Supplementary)	Cracked	195.00 FL	*140.00 FL
30	1		*FRONT TYRE (Supplementary)	Serviceable	580.00 FS	*- FS
31	1		*LEFT FRONT FOOT REST HOLDER (Supplementary)	Bent	165.00 FL	*165.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,238.00	3,513.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	390.10	288.60
Total Parts (\$\$)	4,847.90	3,224.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	800.00	300.00
3	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
4	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT SPORT RIMS	New	150.00	50.00
6	SPRAY PAINTING	New	280.00	200.00
7	LABOUR FOR REMOVING AND REPLACING SUPPLEMENTARY PARTS (Supplementary)	New	150.00	70.00
			Gross Labour Cost (\$\$)	2,040.00
				620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >