

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG21000169/T1VD3Q2

**Date:** 31/03/2021

### REFERENCE

Insured/Claimant:	KUEK JU HUAT	Policy No:	29141234QMY
Date of Loss:	02/01/2021	Nature of Claim:	OD
		Claim No:	632857

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFK6800P</b>		
Make & Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Engine No:	27091031944069
Reg. Date:	20/01/2020 (Man. Year: 2019)	Chassis No:	WDC1569422J685624
Colour:	Grey	Odometer:	8424 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/45 R19	Rear Tyre Size:	235/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,300.00	1,060.79	239.21	18.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	972.00	328.00	25.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,600.00</b>	<b>2,032.79</b>	<b>567.21</b>	<b>21.82</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>2,100.00</b>	<b>1,532.79</b>	<b>567.21</b>	<b>27.01</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>147.00</b>	<b>107.30</b>	<b>39.70</b>	<b>27.01</b>
<b>Nett Amount (S\$)</b>	<b>2,247.00</b>	<b>1,640.09</b>	<b>606.91</b>	<b>27.01</b>

### INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 05/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd  
(Alexandra)  
241 Alexandra Road  
Singapore 159931

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2021)
<b>Parts:</b>	M1-SUV	MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFK6800P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE WIRING HARNESS	Torn	1,300.00 FS	*1,060.79 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>1,300.00</b>	<b>1,060.79</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR REPACE ENGINE WIRING HARNESS	New	1,300.00	972.00
<b>Gross Labour Cost (S\$)</b>			<b>1,300.00</b>	<b>972.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >