

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21000171/T1TD3N2**Date:** 28/10/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001308095
Claimant Vehicle No :	SLU4533A	Insured Vehicle No :	SGR4972R
Date of Loss:	03/01/2021	Nature of Claim:	TP
		Claim No:	251623

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU4533A	Engine No:	LEB5963739
Make & Model:	HONDA VEZEL, 1.5 X A (A)	Chassis No:	RU31263719
Reg. Date:	01/12/2017 (Man. Year: 2017)	Odometer:	257786 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Rassurer 6 mm	Rear Left Side:	Rassurer 6 mm
Front Right Side:	Rassurer 6 mm	Rear Right Side:	Rassurer 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,600.56	5,633.68	5,966.88	51.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	2,330.00	2,620.00	52.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,550.56	7,963.68	8,586.88	51.88
Approved Total (Overridden) (S\$)		6,350.00		
(S\$)	16,550.56	6,350.00	10,200.56	61.63
+ GST 7.00/7.00% (S\$)	1,158.54	444.50	714.04	61.63
Nett Amount (S\$)	17,709.10	6,794.50	10,914.60	61.63

INSPECTION

Date of Assignment:	05/01/2021	
Date Inspected:	06/01/2021 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2021)
Parts: M1-SUV	HONDA VEZEL 1.5 X A (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLU4533A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,050.00 FL	*953.30 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	198.00 FL	*120.00 FL
3	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	50.00 FL	*50.00 FL
4	1		*TAILGATE EMBLEM (VEZEL)	Necessary	89.00 FL	*89.00 FL
5	2		*TAILGATE STOPPER	Not Necessary	50.00 FL	*- FL
6	1		*TAILGATE INNER TRIM	Deformed	477.60 FL	*175.50 FL
7	1		*TAILGATE POCKER HANDLE	Not Necessary	98.60 FL	*- FL
8	1		*TAILGATE INNER LOCK	Bent	665.00 FL	*180.00 FL
9	1		*TAILGATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
10	1		*TAILGATE LOCK DETECTOR	Not Necessary	317.90 FL	*- FL
11	1		*TAIL LAMP	N/s Cracked/O/s Not Necessary	1,164.80 FL	*460.60 FL
12	1		*REAR BUMPER	Deformed	598.50 FL	*549.20 FL
13	2		*REAR BUMPER SIDE RETAINER	Cracked	240.00 FL	*240.00 FL
14	2		*REAR BUMPER SIDE GARNISH	Torn	511.00 FL	*511.00 FL
15	2		*REAR BUMPER REFLECTOR	Cracked	355.80 FL	*240.00 FL
16	1		*END PANEL	Bent	511.90 FL	*415.60 FL
17	1		*END PANEL TOP TRIM	Deformed	288.70 FL	*101.60 FL
18	1		*REAR ALARM BUZZER	Cracked	321.10 FL	*120.00 FL
19	1		*REAR FLOOR PANEL	Repair	896.50 FL	*- FL
20	1		*REAR FLOOR PANEL TOP BOARD	Deformed	376.50 FL	*285.00 FL
21	2		*REAR FLOOR PANEL TOOL SPONGE	Deformed	822.20 FL	*327.20 FL
22	1		*STOP START BATTERY	Not Necessary	650.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM	Deformed	940.00 FL	*688.40 FL
24	2		*REAR FENDER INNER SHIELD	Torn	397.40 FL	*299.60 FL
25	2		*REAR FENDER ARCH GARNISH	Deformed	511.80 FL	*390.00 FL
26	1		*REAR EXHAUST SILENCER	Repair	658.00 FL	*- FL
27	2		*REAR EXHAUST MOUNTING	Not Necessary	100.00 FL	*- FL
28	1		*REAR EXHAUST GASKET	Not Necessary	45.00 FL	*- FL
29	1		*REAR EXHAUST HEAT PLATE	Not Necessary	217.00 FL	*- FL
30	1		*REAR BUMPER LOWER COVER	Deformed	379.00 FL	*250.00 FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
32	1		*TAILGATE INNER TRIM CLIP	Necessary	40.00 FS	*20.00 FS
33	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
34	1		*END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*END PANEL TOP TRIM CLIP	Necessary	30.00 FS	*10.00 FS
36	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*10.00 FS
38	1		*REAR FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*10.00 FS
39	1		*REAR FENDER ARCH GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
40	1		*REVERSE SENSOR	Not Working	450.00 FS	*200.00 FS
41	1		*TAILGATE WEATHERSTRIP	Torn	298.40 FL	*108.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,265.70	6,944.60
- List Item Discount on L Items 20.00/20.00% (\$)	2,665.14	1,310.92
Total Parts (\$)	11,600.56	5,633.68

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,000.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	150.00	30.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	150.00	120.00
6	REMOVE AND INSTALL TAILGATE MECHANISM AND PART	New	150.00	60.00
7	REMOVE,INSTALL AND CHECK REVERSE SENSOR	New	150.00	30.00
8	REMOVE AND INSTALL CARPET,TRIM AND INTERIOR	New	200.00	60.00
9	REMOVE AND INSTALL REAR EXHAUST	New	150.00	0.00
10	REMOVE BATTERY FOR REPAIR WORK	New	450.00	200.00
			Gross Labour Cost (\$\$)	4,950.00
				2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >