

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000174/UVD3Q2

Date: 25/02/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001155646

Claimant
Vehicle No : GBE7788P

Insured Vehicle No : GBH9411Y

Date of Loss: 04/12/2020

Nature of Claim: TP

Claim No: 250978

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE7788P**

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M)

Engine No: 4P10C03955

Reg. Date: 29/03/2016 (Man. Year: 2016)

Chassis No: FEA01BA20086

Colour: Blue

Odometer: 169484 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 195R15(D)

Front Left Side: Austone 6 mm

Rear Left Side: Austone 6/6 mm

Front Right Side: Austone 6 mm

Rear Right Side: Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,537.20	786.91	750.29	48.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	880.00	380.00	30.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,797.20	1,666.91	1,130.29	40.41
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	2,797.20	1,300.00	1,497.20	53.52

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 03/02/2021 Inspected At:

Liu's Brother Auto Engineering
Workshop (kaki Bukit) (HQ)
Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay
@ Kaki Bt Singapore 417883, Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Feb 2021)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE7788P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR HANDLE	Not Necessary	146.40 F	*- FL
2	1		*FRONT RH DOOR OUTER PROTECTOR	Grazed	365.80 F	*215.21 FL
3	1		*FRONT RH FENDER GARNISH	Grazed	574.00 F	*366.01 FL
4	1		*FRONT RH DROPGATE SUPPORT RUBBER	Missing	101.00 F	*68.00 FL
5	1		*FRONT RH CORPORATE ADVERTISEMENT & ARTWORK	Necessary	350.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,537.20	949.22
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	162.31

Total Parts (S\$)	1,537.20	786.91
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	300.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	600.00	580.00
3	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	0.00
Gross Labour Cost (\$\$)			1,260.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >