

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2103185

3 ANSON ROAD #16-00 INV Date 07/05/2021

SPRINGLEAF TOWER
SINGAPORE 079909
Reference CC3/CTI21000182/T1ra3q2

Code CTI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 1029X

Insured Veh. GBJ 5029J

Claim No. SNM21D200073/LKKDS

Policy No. DMCVSNA00040072001

Accident Date 02/01/2021

Inspection Date 04/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref:	CC3/CTI21000182/T1ra3q2		
	3 ANSON ROAD # SPRINGLEAF TO	16-00 VERSINGAPORE 079909	Date:	07/05/2021		
			Code:	CTI		
1.		Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 5029J	Veh. Inspected	SHD 1029X		
	Policy No.	DMCVSNA00040072001	Coverage (\$)	0.00		
	Claim No.	SNM21D200073/LKKDS	Excess (\$)	0.00		
	Assign From		Assign Date	04/01/2021		
2.	•	Vehicle Partic	culars & Condition			
	Make & Model	KIA OPTIMA	c.c	1685		
	Engine No.	HIDDEN	Year of Reg.	2016		
	Chassis No.	KNAGM414MF5658737	Colour	SILVER		
	Odometer	404324 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	205/65 R15	WEST LAKE	6 mm		
	rarrrone ryro					
	L/H Front Tyre	205/65 R15	WEST LAKE	6 mm		
		205/65 R15 205/65 R15	WEST LAKE WEST LAKE	6 mm		
	L/H Front Tyre			1		
4.	L/H Front Tyre R/H Rear Tyre	205/65 R15 205/65 R15	WEST LAKE	6 mm		
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/65 R15 205/65 R15	WEST LAKE WEST LAKE on of Damages	6 mm		
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/65 R15 205/65 R15  Description STAINED DAMAGES AT THE O/S	WEST LAKE WEST LAKE on of Damages	6 mm		
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SU	205/65 R15  205/65 R15  Description STAINED DAMAGES AT THE O/S ETAILS.	WEST LAKE WEST LAKE on of Damages	6 mm		
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SU	205/65 R15  205/65 R15  Description STAINED DAMAGES AT THE O/S ETAILS.	WEST LAKE WEST LAKE on of Damages BODY.	6 mm		
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUDDAMAGES SEE D	205/65 R15 205/65 R15  Description STAINED DAMAGES AT THE O/S ETAILS.  General	WEST LAKE WEST LAKE On of Damages BODY. Information Inspection Date	6 mm 6 mm		
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUDDAMAGES SEE D Accident Date	205/65 R15  205/65 R15  Description STAINED DAMAGES AT THE O/S ETAILS.  General 02/01/2021	WEST LAKE WEST LAKE On of Damages BODY.  Information Inspection Date ICES PTE LTD	6 mm 6 mm		
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUDDAMAGES SEE D Accident Date	205/65 R15  205/65 R15  Description STAINED DAMAGES AT THE O/S ETAILS.  General 02/01/2021  PREMIER AUTOMOTIVE SERV 23 CHANGI SOUTH AVENUE 2	WEST LAKE WEST LAKE On of Damages BODY.  Information Inspection Date ICES PTE LTD	6 mm 6 mm		
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SUST DAMAGES SEE D  Accident Date Survey held at	205/65 R15  205/65 R15  Description STAINED DAMAGES AT THE O/S ETAILS.  General 02/01/2021  PREMIER AUTOMOTIVE SERV 23 CHANGI SOUTH AVENUE 2	WEST LAKE WEST LAKE On of Damages BODY.  Information Inspection Date ICES PTE LTD #01-02 SINGAPORE 4864 Emarks HOUT PREJUDICE" BASIS	6 mm 6 mm 04/01/2021 43		
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SUST DAMAGES SEE D  Accident Date Survey held at	205/65 R15  Description STAINED DAMAGES AT THE O/S ETAILS.  General 02/01/2021  PREMIER AUTOMOTIVE SERV 23 CHANGI SOUTH AVENUE 2  REDN WAS CONDUCTED ON A"WITCHE TO YOUR INSTRUCTIONS, W	WEST LAKE WEST LAKE On of Damages BODY.  Information Inspection Date ICES PTE LTD #01-02 SINGAPORE 4864 Emarks HOUT PREJUDICE" BASIS	6 mm 6 mm 04/01/2021 43		
5. 5a.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SUDDAMAGES SEE D  Accident Date Survey held at  A)THE INSPECTICE B)IN ACCORDANCE	205/65 R15  Description STAINED DAMAGES AT THE O/S ETAILS.  General 02/01/2021  PREMIER AUTOMOTIVE SERV 23 CHANGI SOUTH AVENUE 2  REDN WAS CONDUCTED ON A"WITCHE TO YOUR INSTRUCTIONS, W	WEST LAKE WEST LAKE On of Damages BODY.  Information Inspection Date ICES PTE LTD #01-02 SINGAPORE 4864 Emarks HOUT PREJUDICE" BASIS E HAVE NOT AUTHORISE Days of Repair	6 mm 6 mm 04/01/2021 43		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1029X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT O/S FENDER	BENT	384.00	384.00
1	FRONT O/S DOOR	TO REPAIR SEE LABOUR	765.00	-
1	O/S MIRROR ASSY	NOT NECESSARY	590.00	-
	LESS 10% DISCOUNT		-173.90	-38.40
			1,565.10	345.60
	SPECIAL NETT ITEMS			
1	FRONT O/S FENDER STICKER (SN)	NECESSARY	30.00	30.00
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			180.00	130.00
	<u>LABOUR</u>			
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF FRONT O/S DOOR INTO NEW SHELL DOOR .	NOT NECESSARY	150.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE FRONT O/S FENDER ,ETC.INCLUSIVE OF THE REPAIR OF FRONT O/S DOOR .		450.00	200.00
	TO PUTTY AND SPRAY PAINTING ON FRONT O/S FENDER ,FRONT O/S DOOR ,O/S SIDE MIRROR .		600.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS .		150.00	30.00
			1,350.00	630.00
	GRAND TOTAL		3,095.10	1,105.60

RECOMMENDED COST OF LUMP SUM REPAIRS		850.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC3/CTI21000182/T1ra3q2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**HO LEONG CHUAN** 

**Automotive Assessor** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 1029X

### **INSPECTION**
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 1029X

### **RE-INSPECTION**







