

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21000186/EBA3Q2

Date: 01/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKL3881K	Insured Vehicle No :	SHA5253D
Date of Loss: 28/12/2020	Nature of Claim: TP	Claim No: MCT20120555

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL3881K		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11BN1023
Reg. Date:	21/01/2020 (Man. Year: 2019)	Chassis No:	GF7W0602232
Colour:	White	Odometer:	10212 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,110.00	2,785.00	1,325.00	32.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	1,730.00	4,250.00	71.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,090.00	4,515.00	5,575.00	55.25
+ GST 7.00/7.00% (S\$)	706.30	316.05	390.25	55.25
Nett Amount (S\$)	10,796.30	4,831.05	5,965.25	55.25
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
Nett Liability (S\$)		5,473.05		

INSPECTION

Date of Assignment:	04/01/2021	
Date Inspected:	12/01/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2021)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL3881K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
2	1		*BODY KIT SEALANT	Not Necessary	80.00 FS	*- FS
3	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
4	1		*REFLECTOR ,TAIL LAMP LH	Broken	100.00 FS	*100.00 FS
5	1		*LAMP ASSY ,COMB ,RR LH	Not Necessary	600.00 FS	*- FS
6	1		*FACE ,RR BUMPER	Dented	807.00 FS	*807.00 FS
7	1		*REINFORCEMENT ,RR BUMPER ,LH	Not Necessary	79.00 FS	*- FS
8	1		*EXTENSION ,RR BUMPER	Cut	292.00 FS	*292.00 FS
9	1		*BRKT ,R/BMPR FACE SIDE ,LH	Broken	12.00 FS	*12.00 FS
10	1		*MOULDING ,RR BUMPER ,LH	Not Necessary	88.00 FS	*- FS
11	1		*MOULDING ,RR WHEEL ARCH ,LH	Not Necessary	168.00 FS	*- FS
12	1		*BODY KIT ,OUTLANDER	Broken	1,554.00 FS	*1,554.00 FS
Total Parts (\$\$)					4,110.00	2,785.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW RR BUMPER & BODY KIT REPAIR LHR FENDER & RR END PNL	New	3,200.00	720.00
2	RESPRAY RR BUMPER ,RR BUMPER BODY KIT ,LHR FENDER & RR END PNL	New	2,200.00	550.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	80.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	280.00
5	REMOVE & REFIT REVERSE SENSOR	New	100.00	100.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			5,980.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >